



# Cisco RF Gateway 1 Software Release Notes, Release 2.02.23

## Overview

### Introduction

Software Release 2.02.23 contains improvements related to PSI table handling, particularly on RF Gateway 1 reboot. DVB Simulcrypt Scrambling is still supported and the 2.02.23 release continues to be 48 QAM channel capable.

### Purpose

The purpose of this document is to notify RF Gateway 1 users of the enhancements included in the current release, and informs users of any special upgrade procedures needed for using Release 2.02.23.

### Audience

This document is intended for system engineers or managers responsible for operating and/or maintaining this product.

### Related Publications

Refer to the following documents for additional information regarding hardware and software.


- *Cisco RF Gateway 1 Configuration Guide*, part number 4025112
- *Cisco RF Gateway 1 System Guide*, part number 4024958

### Safe Operation for Software Controlling Optical Transmission Equipment

If this document discusses software, the software described is used to monitor and/or control ours and other vendors' electrical and optical equipment designed to transmit video, voice, or data signals. Certain safety precautions should be observed when operating equipment of this nature.

For equipment specific safety requirements, refer to the appropriate section of the equipment documentation.

For safe operation of this software, refer to the following warnings.

 **WARNINGS:**

- Ensure that all optical connections are complete or terminated before using this equipment to remotely control a laser device. An optical or laser device can pose a hazard to remotely located personnel when operated without their knowledge.
- Allow only personnel trained in laser safety to operate this software. Otherwise, injuries to personnel may occur.
- Restrict access of this software to authorized personnel only.
- Install this software in equipment that is located in a restricted access area.

### In This Document

- CRC Correction for PAT ..... 3
- Known Issues ..... 4
- Licensing ..... 5
- Upgrade Information ..... 6
- Change History ..... 7
- IP Port Configuration Changes..... 8
- Upgrade Procedure for Customers Running 1.02.09 ..... 9
- IP Port Configuration Parameter Settings ..... 11
- For Information..... 13

## CRC Correction for PAT

The first entry in the PAT, program 0, is reserved for network data and contains the PID of network information table (NIT) packets. Usage of the NIT is optional in MPEG-2 but is mandatory in DVB.


On reboots, PAT play-out was observed with invalid CRC when the NIT PID was specified in the PAT. In other words, after rebooting the RF Gateway 1, the initial PAT play-out (with no programs included) did not have a correct CRC for the PAT table. This was true only when the RF Gateway 1 configuration was set up so that the Network PID was specified in the outgoing PAT. When a program was added to the PAT or when the user manually changed the TSID for an output channel, the PAT was then sent with the correct CRC.

The CRC error was determined to be due an incorrect PAT length computation specifically after reboot. This issue is now resolved and CRC computes normally.

## Known Issues

The following list identifies known limitations planned to be resolved as part of an upcoming GA release (CR118308).

- The RF Gateway 1 web interface is not fully tested with IE-8 and Firefox-3.5 or newer. The RF Gateway 1 web management interface is tested with IE-6 or Firefox-2.0.0.14 and above. Use of Java 1.6.x is also recommended.
- The Summary page displays the unit rear panel with Conditional Access (CA) port enabled/ disabled as green/grey. The CA port indication represents the on/off setting and does not represent actual link status.



- The database Restore feature in 2.02.23 requires disabling trap settings (in the restore from database file prior to release 2.01.09) before starting the restore procedure. This can be done before starting a restore configuration in 2.02.23. The procedure is needed to allow compatibility with the enhanced SNMP version 1 and 2 trap support in 2.02.23.
- SNMP community strings are provided in 2.02.23 to support SNMP v1 and v2 traps. Prior to release 2.01.09, there was a single community string applicable to all five trap receivers configurable for the operator. In release 2.02.11, in addition to supporting SNMPv1 and v2 traps, each of the five trap receivers has a separate configurable trap community string. This may cause a possible loss of SNMP trap community strings during an upgrade or downgrade procedure. An operator should carefully verify their trap community strings when upgrading to 2.02.23 or downgrading from 2.02.23, if they are being used.
- An upgrade to 2.02.23 from pre-2.01.09 automatically enables insertion of the Network PID into the PAT. If this is an issue in the user's system, it may be disabled on the *System/System Configuration* page.
- The system uptime counter rolls over to zero after approximately 49 days of continuous use. This behavior manifests on the web management GUI and via SNMP. The rollover does not cause any operational problems or side-effects on active services.

**Note:** A power cycle or reboot of the RF Gateway 1 resets the system uptime counter as part of normal operation.

## Licensing

After an upgrade to 2.02.23, a system license is required for the following features. Refer to Licensing in the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

- Data streams requiring use of the DOCSIS® Timing Interface
- DVB® Encryption

Most systems delivered with 1.02.20 or later using a data part number include a license file pre-installed at the factory. For these systems, an FTP transfer is not necessary.

All systems delivered prior to 1.02.20 and some systems delivered with 01.02.20 require a license file. This can be obtained from Cisco after an upgrade to 2.02.23. Contact your account representative for details on obtaining your license files.

**Note:** Performing an upgrade without a license file will generate an alarm, informing the user that a license file is not present. The unit continues to function until configuration changes are made. However, performing the upgrade may impact functionality of licensed features.

For systems requiring a license upgrade, a licensing capable RF Gateway 1 provides the operator with a new tree menu, located under the System tab, *License Management*. It provides an FTP mechanism to transfer license files to the device. It is recommended that the operator monitor the file transfer status using feedback from the FTP server.

License Overview							
Type	Installed	Count	Usage	Expiration Date	Remaining Time	Expired	Key
DATA	Yes	1	0	00-000-0000	0	No	
DVB_SCRAMBLING	Yes	1	1	00-000-0000	0	No	

## Upgrade Information

An RF Gateway 1 unit running release 1.02.20 can be upgraded directly to 2.02.23. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for more information. The RF Gateway 1 reboots automatically at the end of the upgrade process. However, when upgrading to 2.02.23 from 1.02.09, an intermediate step of using the bridge release 1.02.19 to arrive at 1.02.20 and finally 2.02.23 must be followed. The bridge release designated as 1.02.19 has been created to provide a secure and robust upgrade path. Releases 1.02.19 (bridge) and 1.02.20 (final) have identical user features and functionality. See *Upgrade Procedure for Customers Running 1.02.09* (on page 9).



**WARNING:**

**Upgrading to 1.02.20 or above directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to be non-operational.**

**Refer to *Known Issues* (on page 4) for SNMP related upgrade, downgrade and database restore considerations.**

## Change History

The following table lists the notable change history in the RF Gateway 1 code base.

<b>Release</b>	<b>Release Date</b>	<b>Feature Update</b>
V02.02.23	Oct 4, 2010	Improved PSI table handling
V02.02.22	Jul 8, 2010	Improvements to MPTS stream handling when the PMT PID or a referenced PID is shared by multiple programs. The RF Gateway 1 now fully supports ROSA EM-driven N+1 QAM redundancy.
V02.02.21	May 14, 2010	Improvements in VOD stream startup timing and support of the IP-MIB. This release adds the GbE loop-through feature per port pair with “configurable” redundancy parameters.
V02.02.19	Mar 12, 2010	Improvements in GbE port-pair operation in regards to redundancy and recovery. It also provides a new loop-through feature per port pair for GbE traffic only. This release also provides IGMP implementation enhancements resulting in efficient IGMP message handling.
V02.02.16	Nov 13, 2009	Enhancements enabling stream support for up to 32 PIDs and allowing pass through of non-remapped MPTS streams (with more than 32 PIDs). This release includes license-upgradeable data features and a user authentication feature for UI interface security.
V02.02.11	Jul 20, 2009	Support for four independent input GbE ports and four multicast source IP addresses for Video Map configuration.
V02.01.09	Apr 20, 2009	DVB scrambling support is fully available.

## IP Port Configuration Changes

There is a bug in 1.02.09 that causes the following IP port configuration parameters to have inverted values saved in the configuration file.

- Negotiation Mode (On/Off) - one for each port (total 4)
- Redundancy Mode (Auto/Manual) - one for each port pair (total 2)
- Revert Mode (Enable/Disable) - one for each port pair (total 2)

For details on these parameters, see Chapter 3, *General Configuration and Monitoring* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

This bug has been corrected in the configuration file in 1.02.19. Upon upgrade to 1.02.19, these three parameters will appear to have changed value as seen in the *System/IP Network* page of the web GUI. As a result, the IP ports may not be configured properly for operation immediately after upgrade (after the subsequent reboot that follows activation).

See *Upgrade Procedure for Customers Running 1.02.09* (on page 9).



## Upgrade Procedure for Customers Running 1.02.09

**WARNING:**

Upgrading to 2.02.23 directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to become non-operational.

- 1 Before starting the upgrade, backup the system configuration. Refer to Chapter 3, *General Configuration and Monitoring (Configuration Backup)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. Name the file appropriately to identify it as a configuration that corresponds to 1.02.09. This file will be necessary later if the user decides to revert back to 1.02.09.
- 2 Record the IP port configuration parameters by saving a screen capture of the *System/IP Network* page. See **Recording IP Port Configuration Settings** (on page 12).
- 3 Download and activate 1.02.19. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. The RF Gateway 1 reboots automatically at the end of the upgrade process.
- 4 After reboot, display the *System/IP Network* page. See **Displaying IP Port Configuration Settings** (on page 11).
- 5 Verify the IP port configuration parameters by checking them against those recorded in step 2 (prior to the upgrade as done in step 3). The Negotiation Mode, Redundancy Mode, and Revert Mode parameter values are inverted. See **Displaying IP Port Configuration Settings** (on page 11). Change the differing parameter values to match those recorded before download and activation. Be sure to click **Apply** after making your changes.
- 6 Once step 5 is completed, save the configuration which includes the IP port configuration parameters. Going forward, these values will not change.
- 7 Validate/qualify/soak release 1.02.19 in its application to establish confidence the release is operating at the same level as 1.02.09. In the very unlikely event that service is impacted by 1.02.19, reverting back to 1.02.09 may be done to re-establish operations. If reverting back to 1.02.09 is necessary, the IP port configuration parameters must be swapped back and the configuration saved in step 2 restored.

## Upgrade Procedure for Customers Running 1.02.09

- 8 After satisfactory completion of step 7, upgrade from 1.02.19 to 1.02.20. These two releases have identical performance and behavior. Release 1.02.20 includes a boot code upgrade that readily supports future roadmap features/releases without the need for subsequent two-step bridge upgrade processes.
- 9 Download and activate 2.01.09. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. The RF Gateway 1 reboots automatically at the end of the upgrade process.

## IP Port Configuration Parameter Settings

The RF Gateway 1 has four physical GbE input ports that receive video and data streams from the upstream network. These ports may be used independently (in software releases 02.02.23 or later) or configured to implement input redundancy. See Chapter 3, *General Configuration and Monitoring of the Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for specific details.

### Displaying IP Port Configuration Settings

Follow these instructions to display the *System/IP Network* page.

- 1 Launch your web browser.
- 2 In the IP Address field, enter the RF Gateway 1 IP address.
- 3 Click **Enter**.
- 4 Click the *System/IP Network* tab and review the IP settings. Refer to the following screen.

The screenshot displays the configuration page for 'rfgw-1d'. The left sidebar shows a navigation menu with 'IP Network' selected. The main content area is divided into several sections:

- 10/100 Ports:** A table with columns for Management and Conditional Access. Fields include Port Control, Address Selection Mode, MAC Address, IP Address, Subnet Mask, and Default Gateway.
- Port Pair Configuration:** A table with columns for Port Pair 1 and Port Pair 2. Fields include Video/Data IP, Redundancy Mode (highlighted with a red box), Primary Port, Current Active Port, Redundancy Configuration, Detection Mode, LOS Timeout (s), Revert To Primary (highlighted with a red box), and Revert Check Time (s).
- GbE Input Ports:** A table with columns for Port 1, Port 2, Port 3, and Port 4. Fields include Port Configuration, MAC Address, IP Address, Subnet Mask, and Negotiation Mode (highlighted with a red box).

## Recording IP Port Configuration Settings

Follow these instructions to record IP port configuration settings.

- 1 Navigate to the *System/IP Network* page.
- 2 Click the **Alt-PrtScrn** keys to copy the IP Network parameter settings to the clipboard.
- 3 Launch Microsoft Word (or WordPad if you don't have Microsoft Word) and paste the clipboard contents to page 1.
- 4 Save the Microsoft Word document as ipsettings.doc.

## For Information

### Support Telephone Numbers

This table lists the Technical Support and Customer Service numbers for your area.

Region	Centers	Telephone and Fax Numbers
North America	Cisco Services Atlanta, Georgia United States	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> <li>■ Toll-free: 1-800-722-2009</li> <li>■ Local: 678-277-1120 (Press <b>2</b> at the prompt)</li> </ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"> <li>■ Toll-free: 1-800-722-2009</li> <li>■ Local: 678-277-1120 (Press <b>3</b> at the prompt)</li> <li>■ Fax: 770-236-5477</li> <li>■ Email: customer-service@cisco.com</li> </ul>
Europe, Middle East, Africa	Belgium	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 32-56-445-197 or 32-56-445-155</li> <li>■ Fax: 32-56-445-061</li> </ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 32-56-445-444</li> <li>■ Fax: 32-56-445-051</li> <li>■ Email: service-elc@cisco.com</li> </ul>
Japan	Japan	<ul style="list-style-type: none"> <li>■ Telephone: 81-3-5908-2153 or +81-3-5908-2154</li> <li>■ Fax: 81-3-5908-2155</li> </ul>
Korea	Korea	<ul style="list-style-type: none"> <li>■ Telephone: 82-2-3429-8800</li> <li>■ Fax: 82-2-3452-9748</li> <li>■ Email: songk@cisco.com</li> </ul>
China (mainland)	China	<ul style="list-style-type: none"> <li>■ Telephone: 86-21-2401-4433</li> <li>■ Fax: 86-21-2401-4455</li> <li>■ Email: xishan@cisco.com</li> </ul>
All other Asia Pacific countries & Australia	Hong Kong	<ul style="list-style-type: none"> <li>■ Telephone: 852-2588-4746</li> <li>■ Fax: 852-2588-3139</li> <li>■ Email: saapac-support@cisco.com</li> </ul>
Brazil	Brazil	<ul style="list-style-type: none"> <li>■ Telephone: 11-55-08-9999</li> <li>■ Fax: 11-55-08-9998</li> <li>■ Email: fattinl@cisco.com or ecavalhe@cisco.com</li> </ul>
Mexico, Central America, Caribbean	Mexico	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 52-3515152599</li> <li>■ Fax: 52-3515152599</li> </ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 52-55-50-81-8425</li> <li>■ Fax: 52-55-52-61-0893</li> <li>■ Email: sa-latam-cs@cisco.com</li> </ul>

## For Information

<b>Region</b>	<b>Centers</b>	<b>Telephone and Fax Numbers</b>
All other Latin America countries	Argentina	For <i>Technical Support</i> , call: <ul style="list-style-type: none"><li>■ Telephone: 54-23-20-403340 ext 109</li><li>■ Fax: 54-23-20-403340 ext 103</li></ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"><li>■ Telephone: 770-236-5662</li><li>■ Fax: 770-236-5888</li><li>■ Email: keillov@cisco.com</li></ul>





Cisco Systems, Inc.  
5030 Sugarloaf Parkway, Box 465447  
Lawrenceville, GA 30042

678 277-1120  
800 722-2009  
[www.cisco.com](http://www.cisco.com)

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks).

DOCSIS is a registered trademark of Cable Television Laboratories, Inc.

DVB is a registered trademark of the DVB Project.

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2010 Cisco and/or its affiliates. All rights reserved.  
December 2010

Printed in United States of America  
Part Number 7019739 Rev A