

# Cisco Cisco IOS XR 5.3.4 (Build 1) - Denial of Service (DoS) Vulnerability



Severity: **High**  
ID: cisco-sa-20180131-ipv6

[CVE-2018-0136](#)

Published: 2018-01-31 16:00

Version: IPv6 1.0 : Final

CVSS v3 Score: [8.6](#)

Workarounds: No workarounds available

Cisco ID: [CSCvg46800](#)

This advisory is being released in red text to prevent disclosure of sensitive information.

## Affected Products

Cisco Cisco IOS XR 5.3.4 (Build 1) - Denial of Service (DoS) Vulnerability

## Affected Products

This advisory is being released in red text to prevent disclosure of sensitive information.

This advisory is being released in red text to prevent disclosure of sensitive information.

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180131-ipv6>

€©²å¹½“€£¹½å“◆?

è, † å ¼ ± æ € § ã ◊ ® ã ◊ , ã , « è £ ½ å “ ◊

æœ¬è,†å¼±æ€§ã?¬ã€♦ã·ã,¹ã,³ã,çã,ºãfªã,²ãf¼ã,·ãf§ãf³ã,µãf¼ãf”ã,¹

ãf«ãf¼ã,¿í¼^ASRí¼‰9000

ā, āfā ūfā ¼ā, °ā «ā Šā „ā | ā€ ā- ā ®ā īā » ¶ā Āæ°ā Ÿā •ā, Āā Ÿā `ā ^ā «ā½±é Ÿā, ā

- Cisco IOS XR ½ƒ•ƒ^ã, |ã,§ã,¢ ƒ^ãƒ^ãƒ^ã,¹ 5.3.4  
ãŒå®Ýè|Œã•ã,Œã |ã„ã,  
• ƒ«ƒ^ã,¿ã« Trident ƒ™ƒ^ã,¹ ƒƒ@ã,¤ãƒ³  
ã,«ãƒ^ãƒ‰ãŒæÙè¼%oã•ã,Œã |ãŠã,Šã€IPv6  
ãÙ§è „å®šã•ã,Œã |ã„ã,  
•

## Cisco IOS XR 1/2af•af^a,|a,§a,c af^aaf^aaf^1/4a,1a♦®å^¤å^¥

Cisco IOS XR 1.2.0  
show version

Cisco IOS XR 1.2.1f • Cisco IOS Software

ã€◊ã◊^a◊©ã◊®ã◊tã,ã,1ã◊^ã◊Œè¡”ç¤°ã◊•ã,Œã◊¾ã◊™ã€,ã◊f◊äf◊ã,¤ã,1ã◊§ç◊¾åœ”å®ÿè¡Œã◊  
ã,¤ãf;ã◊f¼ã, ,ã◊f•ã,¡ã,¤ãf«ã◊®å’æ‰€ã◊”å◊å‰øã◊—ã€◊ã€ŒSystem image file  
isã◊ã◊®æ”“ã◊«è¡”ç¤°ã◊•ã,Œã◊¾ã◊™ã€,ã◊f◊äf¼ã◊f‰oo, |ã,§ã,çèŒ½å”ã◊ã◊®å◊å‰øã◊—  
ã,¤ãf;ã◊f¼ã, ,ã◊f•ã,¡ã,¤ãf«ã◊å◊ã◊®æ¬ã◊®è¡Œã◊«è¡”ç¤°ã◊•ã,Œã◊¾ã◊™ã€,

æ¬|ã◊«ã€◊Cisco IOS XR ½ãƒ•ãƒ^ã, |ã,§ã,¢ ãƒªãƒªãƒ¼ã,¹ 5.3.4

ã♦Œå®Ÿè;Œä♦•ã,Œä♦|ã♦„ã,«äf‡äf♦ã,¤ã,¹ã♦§ã♦® show version

ä,³äfžäf³äf%oä♦®å‡ºåŠ›ä¾«ä,'ç¤ºä♦—ä♦¾ä♦™ä€,

<#root>

RP/0/RSP0/CPU0:ASR9001#

**show version**

Wed Jan 24 01:32:32.751 EST

Cisco IOS XR Software, Version 5.3.4

[Default]

Copyright (c) 2017 by Cisco Systems, Inc.

ROM: System Bootstrap, Version 2.04(20140227:092320) [ASR9K ROMMON],

ASR9001 uptime is 6 hours, 17 minutes

System image file is "bootflash:disk0/asr9k-os-mbi-5.3.4.sp4-1.0.0/0x100000/mbiasr9k-rp.vmp"

cisco ASR9K Series (P4040) processor with 8388608K bytes of memory.

P4040 processor at 1500MHz, Revision 2.0

ASR-9001 Chassis

2 Management Ethernet

8 TenGigE

20 GigabitEthernet

8 DWDM controller(s)

8 WANPHY controller(s)

44 GigabitEthernet/IEEE 802.3 interface(s)

219k bytes of non-volatile configuration memory.

2880M bytes of hard disk.

3932144k bytes of disk0: (Sector size 512 bytes).

Configuration register on node 0/RSP0/CPU0 is 0x2102

Cisco ASR 9000

Trident

Processor: P4040

Memory: 8388608K bytes of memory.

- A9K-40GE-L
- A9K-40GE-B
- A9K-40GE-E
- A9K-4T-L
- A9K-4T-B
- A9K-4T-E
- A9K-8T/4-L
- A9K-8T/4-B
- A9K-8T/4-E
- A9K-2T20GE-L

- A9K-2T20GE-B
  - A9K-2T20GE-E
  - A9K-8T-L
  - A9K-8T-B
  - A9K-8T-E
  - A9K-16/8T-B

ASR 9000 à,·äf<sup>a</sup>äf<sup>1/4</sup>ä,º äf«äf<sup>1/4</sup>ä,¿ä«æ◊è½‰ä◊•ä,Cä◊|ä◊,,ä,<äf©ä,¤äf<sup>3</sup> ä,«äf½äf‰ä◊CÉ  
Trident äf™äf<sup>1/4</sup>ä,¹ä◊®ä,,ä◊®ä◊<ä,'ç°èª◊ä◊™ä,<ä◊«ä◊—ä€◊ç®¡ç◊†è€...ä◊— show diag  
|| include

**PID:** ã'äfžäf<sup>3</sup>äf‰oã,'ä½;c””ä♦—ä♦¾ä♦™ä€,äf‡äf♦ã,¤ã,¹ä♦Œå½±éÝ¿ã,'å♦—ä♦'ã,«å♦`ä♦^ä♦`—ä€♦  
Trident äf™äf¼ã,¹ äf©ã,¤äf<sup>3</sup> ä,«äf¼äf‰oã♦®èf½å”♦ IDi½^PIDi½‰oã♦Œä€♦1  
ä♦¤ä»¥ä,Šå♦«ä♦¾ä,Œä♦¾ä♦™ä€,æ¬jä♦®ä¾ä¤äŠã♦`—ä€♦A9K-8T-L  
ä♦®ã,«äf¼äf‰oã♦Œäf‡äf♦ã,¤ã,¹ä♦Šã,cã,`—äftã,£äf-ä♦«ä♦`ä♦`£ä♦`|ä♦,,ä♦¾ä♦™ä€,

<#root>

```
RP/0/RSP0/CPU0:ASR9006-B#show diag | include PID:
```

Tue Jan 26 00:07:09.406 EST

PID: A9K-RSP440-SE

PID: A9K-RSP440-SE

PID: A9K-8X100GE-SE

PID: A9K-8T-L

PID: A9K-36X10GE-SE

PID: A9K-MOD160-TR

PID: A9K-MPA-8X10GE

PID: A9K-MPA-8X10GE

RP/0/RSP0/CPU0:ASR9006-B#

Trident<sup>TM</sup> f<sup>1/4</sup>, 9000 Series Line Card Types  
<https://www.cisco.com/c/en/us/support/docs/routers/asr-9000-series-aggregation-services-routers/116726-qanda-product-00.html>

af‡af♦ã,¤ã,¹ã♦Œ IPv6

show ipv6 interface brief

ã, ãfžã, f³ãf%oã, 'ã½;ç'"ã◊—ã◊ | ã€◊ã, ¶ãf³ã, ;ãf¼ãf•ã, §ã, ¶ã, 'ã◊§ IPv6

ãf~ãf©ãf•ã, fãffã, ~ã®å‡!ç‡†ã‡Œæœ‰åŠ¹ã‡«ã‡ã‡fã‡|ã‡,,ã, <ã‡<ã,'ç‡è‡ã‡§ã‡  
ã‡Œå‡!ç‡†ã‡§ã‡ã, <ã, ^ã‡†ã‡«è „å®šã‡•ã, Œã‡Ýã, ãf‡ã, ;ãf%4f•ã, §ã, ã, 1ã‡®ä¾ã, 'æ-;ã‡

```
RP/0/RP0/CPU0:router# show ipv6 interface brief  
GigabitEthernet0/2/0/0 [Up/Up]  
fe80::212:daff:fe62:c150  
202::1
```

show ipv6 interface brief

ãœæ,µãƒœãƒ¼ãƒ~ãœ•ã,Œãœ|ãœ„ãœ^ãœ„å`åœ^ãœ€ãœ,“ãƒ©ãƒ½ãœf;ãœffãœ»ãœf½ãœ,ãœŒç"ãœ^ãœãœ•ãœFãœ³ãœ™ãœ,ãœ³/ãœÝãœ€œIPv6

ãšœŒc :æšš'ãšœ«ãšœæšœfãšœ'ãšœ ãšœ åšœ åšœ^ãšœ-ãšœœTPy6

ã Cãf%0ãf\_ã 'æŒ‡ã‡ã gãf³ã ;ãf¼ãf•ã ãã gã ¹ã‡Œã

a,øaf<sup>3</sup>a,æaf<sup>4</sup>af•a,sa,øa,`a<sup>4</sup>æaj<sup>4</sup>æj-æj%oaj«a<sup>4</sup>øa,€ej<sup>4</sup> a,,,æ<sup>4</sup>VRH½ Virtual Routing and Forwardingï¼‰øa,øaf<sup>3</sup>a,`a,æaf<sup>3</sup>a,`a<sup>4</sup>øsã<sup>4</sup>,a,øa`^a<sup>4</sup>-`a€<sup>4</sup>IPv6

**show ipv6 interface brief**

**show ipv6 vrf all interface**

VRF ã,¤ãf³ã,¹ã,ãf³ã,¹ã,'ã%o²ã,Šå½“ã♦ | ã,%oã,Cæ♦Ýã,¤ãf³ã,¿ãf¼ãf•ã,§ã,¤ã,¹ã♦Cæ IPv6

show ipv6 vrf all interface

```
RP/0/RP0/CPU0:Router#show ipv6 vrf all interface
```

Bundle-Ether4.765 is Up, ipv6 protocol is Up, Vrfid is FDA (0x60000001)

IPv6 is enabled, link-local address is fe80::21d:a2ff:aabb:ccdd

Global unicast address(es):

2001:db8:1:1::1, subnet is 2001:db8:1:1::/64

Joined group address(es): ff02::1:ff00:0 ff02::1:aabb:ccdd ff02::2

ff02::1

MTU is 1518 (1500 is available to IPv6)

ICMP redirects are disabled

ICMP unreachable messages are enabled

ND DAD is enabled, number of DAD attempts 1

ND reachable time is 0 milliseconds

ND advertised retransmit interval is 0 milliseconds

Hosts use stateless autoconfig for addresses.

Outgoing access list is not set

Inbound access list is not set

Table Id is 0xe0800001

è,,†å¼±æ€§ã,’å♦«ã,“ã♦§ã♦,,ã♦ªã♦,,ã♦“ã♦”ã♦CEçÇºèª♦ã♦•ã,Œã♦ÝèF½å”♦  
ää»—ã♦®ã,·ã,¹ã,³èF½å”♦ã♦«ã♦§ã♦,,ã♦|ã€♦ã♦“ã♦®ã,çãf%oãf♦ã,¤ã,¶ãfã♦®å½±éÝ¿ã,’å♦—ã

Cisco ã,¢ã,°ãfªã,²ãf¼ã,·ãf§ãf³ ã,ãf¼ãf“ã,¹ ãf«ãf¼ã,çi¼^ASRi¼‰9000  
ã,·ãfªãf¼ã,ºã♦§ã€♦Trident ãf™ãf¼ã,¹ ãf©ã,¤ãf³  
ã,«ãf¼ãf‰oã♦CEæ♦è¼‰oã♦•ã,Œã♦|ã♦,,ã♦ªã♦,,å’å♦^ã€♦Cisco IOS XR  
ã,½ãf•ãf^ã,|ã,§ã,çãfªãf¼ã,¹ 5.3.4 ã,’å®Ýè;Œã♦—ã♦|ã♦,,ã♦ªã♦,,å’å♦^ã€♦IPv6  
ã,’æœ‰oåŠ¹ã♦«ã♦—ã♦|ã♦,,ã♦ªã♦,,å’å♦^ã♦—å½±éÝ¿ã,’å♦—ã♦’ã♦¾ã♦>ã,“ã€,

ää»—ã♦®ãf‡ãf♦ã,¤ã,¹ã♦§ã€♦Cisco IOS XR  
ã,½ãf•ãf^ã,|ã,§ã,çã,’å®Ýè;Œã♦—ã♦|ã♦,,ã,å’å♦^ã♦—å½±éÝ¿ã,’å♦—ã♦’ã♦¾ã♦>ã,“ã€,

## ã,»ã,ãf¥ãfªãf†ã,£ä¾µ®³ã♦®ç—•è·í

æœ¬è,,†å¼±æ€§ã,’å♦æ£å^ç”“ã♦™ã,<ã♦”ã♦”ã♦§ã€♦Trident ãf™ãf¼ã,¹ ãf©ã,¤ãf³  
ã,«ãf¼ãf‰oã♦CEãfªãf¼ãf‰oã♦•ã,Œã€♦æ¬jã♦«ç¤ºã♦™ã,^ã♦†ã♦ªé|žä¼å♦®ã,“ãf©ãf¼  
ãf|ãffã,»ãf¼ã,ã♦CEç”Ýæ^ã♦•ã,Œã♦¾ã♦™ã€,

LC/0/6/CPU0:pfm\_node\_lc[285]: %PLATFORM-DIAGS-0-LC\_NP\_LOOPBACK\_FAILED\_RX\_PATH : Set|online\_diag\_lc[16392]  
LC/0/6/CPU0:prm\_server\_tr[296]: %PLATFORM-NP-0-INIT\_ERR : \*\*\* Error 0xA0003F03 : prm\_np\_fast\_reset : Ch  
LC/0/6/CPU0:prm\_server\_tr[296]: %PLATFORM-NP-4-FAULT : Line card needs to be reloaded, a reboot is being

LC/0/5/CPU0:prm\_server\_tr[296]: %PLATFORM-NP-0-INIT\_ERR : \*\*\* Error 0xA0003F03 : prm\_np\_fast\_reset : Ch  
LC/0/5/CPU0:prm\_server\_tr[296]: %PLATFORM-NP-4-FAULT : Line card needs to be reloaded, a reboot is being  
LC/0/5/CPU0:syslog\_dev[88]: prm\_server\_tr[296] PID-163922: reboot internal start: cause code 27 cause F

ã♦”ã,Œã,%oã♦@ãf|ãffã,»ãf¼ã,ã♦Œå®Ýéš>ã♦®ã,ã♦æ£å^ç”“ã,’ç¤ºã♦™ã,,ã♦®ã♦<ã♦©ã♦†ã♦<æ

## å›žé♦¿ç-

ã♦”ã♦®è,,†å¼±æ€§ã♦«å”¾å‡|ã♦™ã,<å›žé♦¿ç-ã♦—ã♦,ã,§ã♦¾ã♦>ã,“ã€,

## ã¿®æ£æ,^ã♦¿ã,½ãf•ãf^ã,|ã,§ã,ç

ã,·ã,¹ã,³ã”ã♦”ã♦®ã,çãf‰oãf♦ã,¤ã,¶ãfã♦“è”“è¼‰oã♦•ã,Œã♦Ýè,,†å¼±æ€§ã♦«å”¾å‡|ã♦™ã,<ç„j  
ãf♦ãf¼ã,ãf§ãf³ã♦”ãf•ã,£ãf¼ãf♦ãf£  
ã,»ãffãf^ã♦«å”¾ã♦—ã♦|ã♦®ã♦¿ã♦”ã♦ªã,§ã♦¾ã♦™ã€,ã♦¿ã♦®ã,^ã♦†ã♦ªã,½ãf•ãf^ã,|ã,§ã,

Security Advisories and Alerts

Technical Assistance Center

URL ã,’ã”ç”“æ,,♦ã♦♦ã♦ã♦•ã♦,,ã€,

ä;®æfæ, ^ä♦¿äfªäfªäf¼ä,¹

æœ—è, †å¼±æ€§ã»«å—¾å†|ã♦™ã, <ã♦Ýã, ♦ã♦®ã, ½ãƒ·ãƒ^ã, |ã, §ã, c ãƒ|ãƒ³ãƒ†ãƒšãƒ³ã, <sup>1</sup>  
ã, c ãƒfãƒ—ã, °ãƒ—ãƒ¼ãƒ%oï¼^SMUï¼%oã♦Œç”“ æ,,♦ã♦•ã,Œã♦|ã♦„ã♦¾ã♦™ã€,ã♦¾ã♦Ýã€♦Cisco  
IOS XR ã, ½ãƒ·ãƒ^ã, |ã, §ã, c ãƒ^ãƒ^ãƒ¼ã, <sup>1</sup> 5.3.4 ã♦®ã, µãƒ¼ãƒ”ã, <sup>1</sup> ãƒãffã, — 7  
ã♦«ã,,ä¿®æ£ã♦Œå♦«ã♦¾ã,Œã♦|ã♦„ã♦¾ã♦™ã€,

IOS XR	SMU ID	SMU
5.3.4	AA13804	<a href="#">asr9k-px-5.3.4.CSCvg46800.tar</a>
5.3.4	AA13870	<a href="#">asr9k-px.5.3.4.sp7.tar</a>

SMU Š, µ, Cisco.com ® [Software Center](#)

[IOS XR Software Maintenance Upgrades \(SMU\)-5.3.4](#) IOS XR

**Service Packs-5.3.4** ã¢«ç§»å•ã¢—ã¢ |ã¢¢ã¢ã¢ „ã¢,

ä ð æ £ å ^ © ç " " ä ° < ä ¾ < å ð " å ... - å ¼ ð ç ™ o è i "

Cisco Product Security Incident Response

å†°å...<sub>5</sub>

ã?“ã?®è„†å¼±æ€§ã? Cisco TAC

ã,µãf?ãf%ãf^ã,±ãf%ã,¹ã?®è§Fæ±ºã,ã?«ç™øè|  
ã?•ã,Œã?¾ã?—ã?Ýã€,

## URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180131-ipv6>

æ”1è..,å±¥æ’

<b>äf♦äf¼ä, äfsäf³</b>	<b>èª¬æ~Ž</b>	<b>ã,»ã, ¯ã,·äf§äf³</b>	<b>ã,¹äf†äf¼ä, ¢ã,¹</b>	<b>æ—¥ä»~</b>
1.0	å^♦å>žå...¬é- <a>äf<sup>a</sup>äf<sup>a</sup>äf<sup>¼</sup>ä,¹</a>	-	Final	2018 å¹' 1 æœ^ 31 æ—¥

å^©ç”“è|◆?ç’„

æœ¬ã, çäf%oãf♦ã,¤ã, ¶ãfªã♦¬ç,,|ä¿♦è”½ã♦®ã,,ã♦®ã♦”ã♦—ã♦|ã♦”æ♦♦ä¾>ã♦—ã♦|ã♦Šã,Šã€  
æœ¬ã, Çãf%oãf♦ã,¤ã, ¶ãfªã♦®æf...å ±ã♦Šã, ^ã♦³ãfªãf³ã,—ã♦®ä½¿ç””ã♦«é-çã♦™ã,<è²¬ä»»ã♦®ä,€  
ã♦¾ã♦Ýã€♦ã,·ã,¹ã,³ã♦—æœ¬ãf%oã,ãf¥ãf;ãf³ãf^ã♦®å†...å®¹ã,’ä°åŠã♦³ã—ã♦«å¤%oæ’ã♦—ã♦  
æœ¬ã, çäf%oãf♦ã,¤ã, ¶ãfªã♦®è”~è¿°å†...å®¹ã♦«é-çã♦—ã♦|æf...å ±é...♦ä¿jã♦® URL  
ã,’çœ♦ç·¥ã♦—ã€♦å°~ç¬ã♦®è»çè¼%oã,,æ,,♦è”³ã,’æ-½ã♦—ã♦Ýå ’å♦”ã€♦å½”ç¤¾ã♦Œç®;ç♦  
ã♦”ã♦®ãf%oã,ãf¥ãf;ãf³ãf^ã♦®æf...å ±ã♦—ã€♦ã,·ã,¹ã,³è£½å”♦ã♦®ã,“ãf³ãf%oãf!ãf¼ã,¶ã,’å”¾è±¡ã

## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。