



# Upgrading the Prisma II ICIM Software to Version R007

## Technical Bulletin

### Overview

---

#### Purpose

This technical bulletin reviews the details of the upgrade of the Prisma II™ ICIM software from version R006 to version R007.

#### The Issue

As of May 2001, version R007 is the latest ICIM software version. Version R007 enhances the features in version R006 and adds support for new features. Version R007 includes the following features.

- The capability to set alarm thresholds from the ICIM keypad.
- Support for ICIM software updates.
- An updated ICIM password system including the capability to enable or disable the User password.
- The capability to communicate manufacturing data to the Transmission Network Control System (TNCS) software.
- Improved response time when communicating with the TNCS software.
- Improved polling rate for updating module status.

#### If You Have Version R006

To fully use the capabilities of the ICIM you will need software version R007. Version R006 is not user upgradeable to version R007. However, if you have version R006 and would like to upgrade, call Cisco Services in your region and request an in-warranty exchange for this product.

---

# For Information

---

## If You Have Questions

If you have technical questions, call Cisco Services for assistance. Follow the menu options to speak with a service engineer.



Cisco Systems, Inc.  
5030 Sugarloaf Parkway, Box 465447  
Lawrenceville, GA 30042

678 277-1120  
800 722-2009  
[www.cisco.com](http://www.cisco.com)

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL:

[www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks).

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Product and service availability are subject to change without notice.

© 2001, 2008, 2012 Cisco and/or its affiliates. All rights reserved.

November 2012 Printed in USA

Part Number 748643 Rev C