

## End-of-Sale and End-of-Life Announcement for the Cisco Catalyst 4500 Series 32-port 10/100BASE-T Line Card and 4-port 100BASE-FX Daughter Card

## EOL5729

Cisco announces the end-of-sale and end-of life dates for the Cisco Catalyst 4500 Series 32-port 10/100BASE-T line card and 4-port 100BASE-FX daughter card. The last day to order the Cisco Catalyst 4500 Series 32-port 10/100BASE-T line card and 4-port 100BASE-FX daughter card is November 26, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin.

Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Catalyst 4500 Series 32-port 10/100BASE-T line card and 4-port 100BASE-FX daughter card. Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for the Cisco Catalyst 4500 Series 32-port 10/100BASE-T line card and 4-port 100BASE-FX daughter card.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.  May 28, 2007	
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 26, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 25, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

HW = Hardware, OS SW = Operating System Software, App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
WS-U4504-FX-MT	Catalyst 4500 4-port 100FX(MTRJ) Uplink for WS-X4232-RJ-XX	WS-X4232-GB-RJ	Catalyst 4500 32-10/100 (RJ-45),2-GE(GBIC)
WS-U4504-FX-MT=	Catalyst 4500 4-port 100FX(MTRJ) Uplink for WS-X4232-RJ-XX	WS-X4232-GB-RJ=	Catalyst 4500 32-10/100 (RJ-45),2-GE(GBIC)
WS-X4232-RJ-XX	Catalyst 4500 10/100 Module,32- ports(RJ45)+Modular uplinks	WS-X4232-GB-RJ	Catalyst 4500 32-10/100 (RJ-45),2-GE(GBIC)
WS-X4232-RJ-XX=	Catalyst 4500 10/100 Module,32- ports(RJ45)+Modular uplinks	WS-X4232-GB-RJ=	Catalyst 4500 32-10/100 (RJ-45),2-GE(GBIC)

## **Product Migration Options**

Customers are encouraged to migrate to the Cisco Catalyst 4500 Series 32-port 10/100BASE-T (RJ-45) with 2-port 1000BASE GBIC line card. Information about this product can be found at: <a href="http://www.cisco.com/en/US/products/hw/switches/ps4324/index.html">http://www.cisco.com/en/US/products/hw/switches/ps4324/index.html</a>

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <a href="http://www.cisco.com/go/tradein/">http://www.cisco.com/go/tradein/</a>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order refurbished equipment program description. html

## For More Information

For more information about the Cisco Catalyst 4500 Series 32-port 10/100BASE-T (RJ-45) with 2-port 1000BASE GBIC line card, visit

http://www.cisco.com/en/US/products/hw/switches/ps4324/index.html, contact your local account representative or send an e-mail to <a href="mailto:ask-c4500-pm@cisco.com">ask-c4500-pm@cisco.com</a>.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod\_end\_of\_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <a href="http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice">http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice</a>



Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com

www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 527-0883 Asia Pacific Headquarters

Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7799 Europe Headquarters

Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: +31 0 800 020 0791 Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, EPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco loS, Cisco Fress, Cisco Systems, Cisco Systems,

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0705R)

Printed in USA C51-400073-01 8/07