

# End-of-Sale and End-of-Life Announcement for the Cisco 1GHz Surge-Gap Taps and Passives

EOL11071

Cisco announces the end-of-sale and end-of-life dates for the Cisco 1GHz Surge-Gap Taps and Passives. The last day to order the affected product(s) is January 9, 2017. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 1GHz Surge-Gap Taps and Passives

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 11, 2016
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 9, 2017
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 9, 2017
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 9, 2018
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 9, 2018
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	April 6, 2021
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	January 31, 2022

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4041857	ASSY, SG RW FP TAP, 2Way, 26F/23R (Pkg of 10)	There is currently no replacement product available for this product.	-	-
4041858	ASSY, SG RW FP TAP, 2Way, 29F/23R (Pkg of 10)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4041859	ASSY, SG RW FP TAP, 2Way, 32F/23R (Pkg of 10)	There is currently no replacement product available for this product.	-	-
4041860	ASSY, SG RW FP TAP, 4Way, 26F/23R (Pkg of 10)	There is currently no replacement product available for this product.	-	-
4041861	ASSY, SG RW FP TAP, 4Way, 29F/23R (Pkg of 10)	There is currently no replacement product available for this product.	-	-
4041862	ASSY, SG RW FP TAP, 4Way, 32F/23R (Pkg of 10)	There is currently no replacement product available for this product.	-	-
753370	Surge-Gap Tap, 2way, 4dB (Mult=20)	SG-TAP-2-04-STD	Surge-Gap Tap, 1.25GHz, 2way, 4dB (Mult=20)	-
753371	Surge-Gap Tap, 2way, 8dB (Mult=20)	SG-TAP-2-08-STD	Surge-Gap Tap, 1.25GHz, 2way, 8dB (Mult=20)	-
753372	Surge-Gap Tap, 2way, 11dB (Mult=20)	SG-TAP-2-11-STD	Surge-Gap Tap, 1.25GHz, 2way, 11dB (Mult=20)	-
753373	Surge-Gap Tap, 2way, 14dB (Mult=20)	SG-TAP-2-14-STD	Surge-Gap Tap, 1.25GHz, 2way, 14dB (Mult=20)	-
753374	Surge-Gap Tap, 2way, 17dB (Mult=20)	SG-TAP-2-17-STD	Surge-Gap Tap, 1.25GHz, 2way, 17dB (Mult=20)	-
753375	Surge-Gap Tap, 2way, 20dB (Mult=20)	SG-TAP-2-20-STD	Surge-Gap Tap, 1.25GHz, 2way, 20dB (Mult=20)	-
753376	Surge-Gap Tap, 2way, 23dB (Mult=20)	SG-TAP-2-23-STD	Surge-Gap Tap, 1.25GHz, 2way, 23dB (Mult=20)	-
753377	Surge-Gap Tap, 2way, 26dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753378	Surge-Gap Tap, 2way, 29dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753379	Surge-Gap Tap, 4way, 8dB (Mult=20)	SG-TAP-4-08-STD	Surge-Gap Tap, 1.25GHz, 4way, 8dB (Mult=20)	-
753380	Surge-Gap Tap, 4way, 11dB (Mult=20)	SG-TAP-4-11-STD	Surge-Gap Tap, 1.25GHz, 4way, 11dB (Mult=20)	-
753381	Surge-Gap Tap, 4way, 14dB (Mult=20)	SG-TAP-4-14-STD	Surge-Gap Tap, 1.25GHz, 4way, 14dB (Mult=20)	-
753382	Surge-Gap Tap, 4way, 17dB (Mult=20)	SG-TAP-4-17-STD	Surge-Gap Tap, 1.25GHz, 4way, 17dB (Mult=20)	-
753383	Surge-Gap Tap, 4way, 20dB (Mult=20)	SG-TAP-4-20-STD	Surge-Gap Tap, 1.25GHz, 4way, 20dB (Mult=20)	-
753384	Surge-Gap Tap, 4way, 23dB (Mult=20)	SG-TAP-4-23-STD	Surge-Gap Tap, 1.25GHz, 4way, 23dB (Mult=20)	-
753385	Surge-Gap Tap, 4way, 26dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753386	Surge-Gap Tap, 4way, 29dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753387	Surge-Gap Tap, 8way, 11dB (Mult=10)	SG-TAP-8-11-FP	Surge-Gap FP Tap, 1.25GHz, 8way, 11dB (Mult=10)	-
753388	Surge-Gap Tap, 8way, 14dB (Mult=10)	SG-TAP-8-14-FP	Surge-Gap FP Tap, 1.25GHz, 8way, 14dB (Mult=10)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
753389	Surge-Gap Tap, 8way, 17dB (Mult=10)	SG-TAP-8-17-FP	Surge-Gap FP Tap, 1.25GHz, 8way, 17dB (Mult=10)	-
753390	Surge-Gap Tap, 8way, 20dB (Mult=10)	SG-TAP-8-20-FP	Surge-Gap FP Tap, 1.25GHz, 8way, 20dB (Mult=10)	-
753391	Surge-Gap Tap, 8way, 23dB (Mult=10)	SG-TAP-8-23-FP	Surge-Gap FP Tap, 1.25GHz, 8way, 23dB (Mult=10)	-
753392	Surge-Gap Tap, 8way, 26dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753393	Surge-Gap Tap, 8way, 29dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753394	Surge-Gap Faceplate, 2way, 4dB (Mult=20)	SG-TAP-2-04-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 4dB (Mult=20)	-
753395	Surge-Gap Faceplate, 2way, 8dB (Mult=20)	SG-TAP-2-08-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 8dB (Mult=20)	-
753396	Surge-Gap Faceplate, 2way, 11dB (Mult=20)	SG-TAP-2-11-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 11dB (Mult=20)	-
753397	Surge-Gap Faceplate, 2way, 14dB (Mult=20)	SG-TAP-2-14-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 14dB (Mult=20)	-
753398	Surge-Gap Faceplate, 2way, 17dB (Mult=20)	SG-TAP-2-17-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 17dB (Mult=20)	-
753399	Surge-Gap Faceplate, 2way, 20dB (Mult=20)	SG-TAP-2-20-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 20dB (Mult=20)	-
753400	Surge-Gap Faceplate, 2way, 23dB (Mult=20)	SG-TAP-2-23-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 2way, 23dB (Mult=20)	-
753401	Surge-Gap Faceplate, 2way, 26dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753402	Surge-Gap Faceplate, 2way, 29dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753403	Surge-Gap Faceplate, 4way, 8dB (Mult=20)	SG-TAP-4-08-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 4way, 8dB (Mult=20)	-
753404	Surge-Gap Faceplate, 4way, 11dB (Mult=20)	SG-TAP-4-11-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 4way, 11dB (Mult=20)	-
753405	Surge-Gap Faceplate, 4way, 14dB (Mult=20)	SG-TAP-4-14-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 4way, 14dB (Mult=20)	-
753406	Surge-Gap Faceplate, 4way, 17dB (Mult=20)	SG-TAP-4-17-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 4way, 17dB (Mult=20)	-
753407	Surge-Gap Faceplate, 4way, 20dB (Mult=20)	SG-TAP-4-20-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 4way, 20dB (Mult=20)	-
753408	Surge-Gap Faceplate, 4way, 23dB (Mult=20)	SG-TAP-4-23-SFP	Surge-Gap Tap, Faceplate, 1.25GHz, 4way, 23dB (Mult=20)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
753409	Surge-Gap Faceplate, 4way, 26dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753410	Surge-Gap Faceplate, 4way, 29dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753411	Surge-Gap Faceplate, 8way, 11dB (Mult=10)	SG-TAP-8-11-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 8way, 11dB (Mult=10)	-
753412	Surge-Gap Faceplate, 8way, 14dB (Mult=10)	SG-TAP-8-14-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 8way, 14dB (Mult=10)	-
753413	Surge-Gap Faceplate, 8way, 17dB (Mult=10)	SG-TAP-8-17-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 8way, 17dB (Mult=10)	-
753414	Surge-Gap Faceplate, 8way, 20dB (Mult=10)	SG-TAP-8-20-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 8way, 20dB (Mult=10)	-
753415	Surge-Gap Faceplate, 8way, 23dB (Mult=10)	SG-TAP-8-23-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 8way, 23dB (Mult=10)	-
753416	Surge-Gap Faceplate, 8way, 26dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753417	Surge-Gap Faceplate, 8way, 29dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753418	Surge-Gap FP Tap, 2way, 4dB (Mult=10)	SG-TAP-2-04-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 4dB (Mult=10)	-
753419	Surge-Gap FP Tap, 2way, 8dB (Mult=10)	SG-TAP-2-08-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 8dB (Mult=10)	-
753420	Surge-Gap FP Tap, 2way, 11dB (Mult=10)	SG-TAP-2-11-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 11dB (Mult=10)	-
753421	Surge-Gap FP Tap, 2way, 14dB (Mult=10)	SG-TAP-2-14-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 14dB (Mult=10)	-
753422	Surge-Gap FP Tap, 2way, 17dB (Mult=10)	SG-TAP-2-17-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 17dB (Mult=10)	-
753423	Surge-Gap FP Tap, 2way, 20dB (Mult=10)	SG-TAP-2-20-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 20dB (Mult=10)	-
753424	Surge-Gap FP Tap, 2way, 23dB (Mult=10)	SG-TAP-2-23-FP	Surge-Gap FP Tap, 1.25GHz, 2way, 23dB (Mult=10)	-
753425	Surge-Gap FP Tap, 2way, 26dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753426	Surge-Gap FP Tap, 2way, 29dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753427	Surge-Gap FP Tap, 4way, 8dB (Mult=10)	SG-TAP-4-08-FP	Surge-Gap FP Tap, 1.25GHz, 4way, 8dB (Mult=10)	-
753428	Surge-Gap FP Tap, 4way, 11dB (Mult=10)	SG-TAP-4-11-FP	Surge-Gap FP Tap, 1.25GHz, 4way, 11dB (Mult=10)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
753429	Surge-Gap FP Tap, 4way, 14dB (Mult=10)	SG-TAP-4-14-FP	Surge-Gap FP Tap, 1.25GHz, 4way, 14dB (Mult=10)	-
753430	Surge-Gap FP Tap, 4way, 17dB (Mult=10)	SG-TAP-4-17-FP	Surge-Gap FP Tap, 1.25GHz, 4way, 17dB (Mult=10)	-
753431	Surge-Gap FP Tap, 4way, 20dB (Mult=10)	SG-TAP-4-20-FP	Surge-Gap FP Tap, 1.25GHz, 4way, 20dB (Mult=10)	-
753432	Surge-Gap FP Tap, 4way, 23dB (Mult=10)	SG-TAP-4-23-FP	Surge-Gap FP Tap, 1.25GHz, 4way, 23dB (Mult=10)	-
753433	Surge-Gap FP Tap, 4way, 26dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753434	Surge-Gap FP Tap, 4way, 29dB (Mult=10)	There is currently no replacement product available for this product.	-	-
753435	Surge-Gap FP Faceplate, 2way, 4dB (Mult=20)	SG-TAP-2-04-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 4dB (Mult=10)	-
753436	Surge-Gap FP Faceplate, 2way, 8dB (Mult=20)	SG-TAP-2-08-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 8dB (Mult=10)	-
753437	Surge-Gap FP Faceplate, 2way, 11dB (Mult=20)	SG-TAP-2-11-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 11dB (Mult=10)	-
753438	Surge-Gap FP Faceplate, 2way, 14dB (Mult=20)	SG-TAP-2-14-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 14dB (Mult=10)	-
753439	Surge-Gap FP Faceplate, 2way, 17dB (Mult=20)	SG-TAP-2-17-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 17dB (Mult=10)	-
753440	Surge-Gap FP Faceplate, 2way, 20dB (Mult=20)	SG-TAP-2-20-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 20dB (Mult=10)	-
753441	Surge-Gap FP Faceplate, 2way, 23dB (Mult=20)	SG-TAP-2-23-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 2way, 23dB (Mult=10)	-
753442	Surge-Gap FP Faceplate, 2way, 26dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753443	Surge-Gap FP Faceplate, 2way, 29dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753444	Surge-Gap FP Faceplate, 4way, 8dB (Mult=20)	SG-TAP-4-08-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 4way, 8dB (Mult=10)	-
753445	Surge-Gap FP Faceplate, 4way, 11dB (Mult=20)	SG-TAP-4-11-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 4way, 11dB (Mult=10)	-
753446	Surge-Gap FP Faceplate, 4way, 14dB (Mult=20)	SG-TAP-4-14-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 4way, 14dB (Mult=10)	-
753447	Surge-Gap FP Faceplate, 4way, 17dB (Mult=20)	SG-TAP-4-17-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 4way, 17dB (Mult=10)	-
753448	Surge-Gap FP Faceplate, 4way, 20dB (Mult=20)	SG-TAP-4-20-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 4way, 20dB (Mult=10)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
753449	Surge-Gap FP Faceplate, 4way, 23dB (Mult=20)	SG-TAP-4-23-FFP	Surge-Gap FP Tap, Faceplate, 1.25GHz, 4way, 23dB (Mult=10)	-
753450	Surge-Gap FP Faceplate, 4way, 26dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753451	Surge-Gap FP Faceplate, 4way, 29dB (Mult=20)	There is currently no replacement product available for this product.	-	-
753452	Surge-Gap Rev Wndw Tap, 2way, 26dB F/23dB R (Mult=20)	SG-RW-2-F26R20-STD	Surge-Gap Rev Wndw Tap, 1.25GHz, 2way, F26dB/R20dB (Mult=20)	-
753453	Surge-Gap Rev Wndw Tap, 2way, 29dB F/23dB R (Mult=20)	SG-RW-2-F29R20-STD	Surge-Gap Rev Wndw Tap, 1.25GHz, 2way, F29dB/R20dB (Mult=20)	-
753454	Surge-Gap Rev Wndw Tap, 2way, 32dB F/23dB R (Mult=20)	SG-RW-2-F32R20-STD	Surge-Gap Rev Wndw Tap, 1.25GHz, 2way, F32dB/R20dB (Mult=20)	-
753455	Surge-Gap Rev Wndw Tap, 4way, 26dB F/23dB R (Mult=20)	SG-RW-4-F26R20-STD	Surge-Gap Rev Wndw Tap, 1.25GHz, 4way, F26dB/R20dB (Mult=20)	-
753456	Surge-Gap Rev Wndw Tap, 4way, 29dB F/23dB R (Mult=20)	SG-RW-4-F29R20-STD	Surge-Gap Rev Wndw Tap, 1.25GHz, 4way, F29dB/R20dB (Mult=20)	-
753457	Surge-Gap Rev Wndw Tap, 4way, 32dB F/23dB R (Mult=20)	SG-RW-4-F32R20-STD	Surge-Gap Rev Wndw Tap, 1.25GHz, 4way, F32dB/R20dB (Mult=20)	-
753458	Surge-Gap Rev Wndw Tap, 8way, 26dB F/23dB R (Mult=10)	SG-RW-8-F26R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 8way, F26dB/R20dB (Mult=10)	-
753459	Surge-Gap Rev Wndw Tap, 8way, 29dB F/23dB R (Mult=10)	SG-RW-8-F29R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 8way, F29dB/R20dB (Mult=10)	-
753460	Surge-Gap Rev Wndw Tap, 8way, 32dB F/23dB R (Mult=10)	SG-RW-8-F32R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 8way, F32dB/R20dB (Mult=10)	-
753461	Surge-Gap Rev Wndw Faceplate, 2way, 26dB F/23dB R (Mult=20)	SG-RW-2-F26R20-SFP	Surge-Gap Rev Wndw Tap, Faceplate, 1.25G, 2w, F26dB/R20dB (Mult20)	-
753462	Surge-Gap Rev Wndw Faceplate, 2way, 29dB F/23dB R (Mult=20)	SG-RW-2-F29R20-SFP	Surge-Gap Rev Wndw Tap, Faceplate, 1.25G, 2w, F29dB/R20dB (Mult20)	-
753463	Surge-Gap Rev Wndw Faceplate, 2way, 32dB F/23dB R (Mult=20)	SG-RW-2-F32R20-SFP	Surge-Gap Rev Wndw Tap, Faceplate, 1.25G, 2w, F32dB/R20dB (Mult20)	-
753464	Surge-Gap Rev Wndw Faceplate, 4way, 26dB F/23dB R (Mult=20)	SG-RW-4-F26R20-SFP	Surge-Gap Rev Wndw Tap, Faceplate, 1.25G, 4w, F26dB/R20dB (Mult20)	-
753465	Surge-Gap Rev Wndw Faceplate, 4way, 29dB F/23dB R (Mult=20)	SG-RW-4-F29R20-SFP	Surge-Gap Rev Wndw Tap, Faceplate, 1.25G, 4w, F29dB/R20dB (Mult20)	-
753466	Surge-Gap Rev Wndw Faceplate, 4way, 32dB F/23dB R (Mult=20)	SG-RW-4-F32R20-SFP	Surge-Gap Rev Wndw Tap, Faceplate, 1.25G, 4w, F32dB/R20dB (Mult20)	-
753467	Surge-Gap Rev Wndw Faceplate, 8way, 26dB F/23dB R (Mult=10)	SG-RW-8-F26R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 8w, F26dB/R20dB (Mult10)	-
753468	Surge-Gap Rev Wndw Faceplate, 8way, 29dB F/23dB R (Mult=10)	SG-RW-8-F29R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 8w, F29dB/R20dB (Mult10)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
753469	Surge-Gap Rev Wndw Faceplate, 8way, 32dB F/23dB R (Mult=10)	SG-RW-8-F32R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 8w, F32dB/R20dB (Mult10)	-
753470	Surge-Gap Rev Wndw FP Tap, 2way, 26dB F/23dB R (Mult=10)	SG-RW-2-F26R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 2way, F26dB/R20dB (Mult=10)	-
753471	Surge-Gap Rev Wndw FP Tap, 2way, 29dB F/23dB R (Mult=10)	SG-RW-2-F29R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 2way, F29dB/R20dB (Mult=10)	-
753472	Surge-Gap Rev Wndw FP Tap, 2way, 32dB F/23dB R (Mult=10)	SG-RW-2-F32R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 2way, F32dB/R20dB (Mult=10)	-
753473	Surge-Gap Rev Wndw FP Tap, 4way, 26dB F/23dB R (Mult=10)	SG-RW-4-F26R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 4way, F26dB/R20dB (Mult=10)	-
753474	Surge-Gap Rev Wndw FP Tap, 4way, 29dB F/23dB R (Mult=10)	SG-RW-4-F29R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 4way, F29dB/R20dB (Mult=10)	-
753475	Surge-Gap Rev Wndw FP Tap, 4way, 32dB F/23dB R (Mult=10)	SG-RW-4-F32R20-FFP	Surge-Gap Rev Wndw FP Tap, 1.25GHz, 4way, F32dB/R20dB (Mult=10)	-
753476	Surge-Gap Rev Wndw FP Faceplate, 2way, 26dB F/23dB R (Mult=20)	SG-RW-2-F26R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 2w, F26dB/R20dB (Mult10)	-
753477	Surge-Gap Rev Wndw FP Faceplate, 2way, 29dB F/23dB R (Mult=20)	SG-RW-2-F29R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 2w, F29dB/R20dB (Mult10)	-
753478	Surge-Gap Rev Wndw FP Faceplate, 2way, 32dB F/23dB R (Mult=20)	SG-RW-2-F32R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 2w, F32dB/R20dB (Mult10)	-
753479	Surge-Gap Rev Wndw FP Faceplate, 4way, 26dB F/23dB R (Mult=20)	SG-RW-4-F26R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 4w, F26dB/R20dB (Mult10)	-
753480	Surge-Gap Rev Wndw FP Faceplate, 4way, 29dB F/23dB R (Mult=20)	SG-RW-4-F29R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 4w, F29dB/R20dB (Mult10)	-
753481	Surge-Gap Rev Wndw FP Faceplate, 4way, 32dB F/23dB R (Mult=20)	SG-RW-4-F32R20-FFP	Surge-Gap Rev Wndw FP Faceplate, 1.25G, 4w, F32dB/R20dB (Mult10)	-

## Product Migration Options

Customers are encouraged to migrate to the 1.25GHz equivalent Taps and Reverse Window Taps. Information about this product can be found at the URLs specified below. Some replacement products may be slightly different in value. If you have questions, please contact your sales or applications engineer. For Surge-Gap products without replacements, you can look for a similar replacement in Flexible Solutions Taps.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

[http://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

---

Customers may be able to continue to purchase the Cisco 1GHz Surge-Gap Taps and Passives through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

### For More Information

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

\*\* For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

### Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



---

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)