

# Troubleshooting de Hardware para os Cisco uBR9xx Series Cable Modems

## Contents

[Introduction](#)

[Prerequisites](#)

[Requirements](#)

[Componentes Utilizados](#)

[Conventions](#)

[Fluxograma de Troubleshooting](#)

[Informações Relacionadas](#)

## [Introduction](#)

Este documento fornece informações de Troubleshooting para falhas comuns de hardware com os modems a cabo Cisco uBR9xx Series e fornece maneiras de solucionar essas falhas. O fluxograma lista os sintomas mais comuns encontrados pelos modems a cabo Cisco uBR9xx Series.

## [Prerequisites](#)

## [Requirements](#)

Não existem requisitos específicos para este documento.

## [Componentes Utilizados](#)

Este documento não se restringe a versões de software e hardware específicas.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

## [Conventions](#)

Consulte as [Convenções de Dicas Técnicas da Cisco para obter mais informações sobre convenções de documentos](#).

## [Fluxograma de Troubleshooting](#)

