

## **PRODUCT BULLETIN NO. 2840**

## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO OPTIMIZED EDGE ROUTING MASTER CONTROLLER ENGINE 1.1

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® Optimized Edge Routing Master Controller Engine 1.1.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement and the migration path to a replacement product.

Information about the replacement product can be found at: http://www.cisco.com/go/oer

Table 1. End-of-Life Milestones and Dates for the Cisco Optimized Edge Master Controller Engine 1.1

Milestone	Definition	Date	
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.		
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.		
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.		
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.		
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.		
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.		
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.		
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 5, 2005	

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
OER-1170-K9	Cisco Optimized Edge Routing Master Controller Engine with OER 1.1 software.	Optimized Edge Routing (OER) available in Cisco IOS® Software Release 12.3(8)T and later.	Cisco IOS Software on Cisco hardware platforms.

## **PRODUCT MIGRATION OPTIONS**

The recommended replacement for the Cisco Optimized Edge Routing Master Controller Engine 1.1 is Cisco IOS Software Release 12.3(8)T and later on the following Cisco hardware platforms:

- Cisco 1700 Series Modular Service Access Router.
- Cisco 1800 Series Integrated Services Router.
- Cisco 2600 Series Multiservice Platform.
- Cisco 2800 Series Integrated Services Router.
- Cisco 3640 and 3660 Multiservice platforms.
- Cisco 3700 Series Multiservice Access Router.
- Cisco 3800 Integrated Services Router.
- Cisco 7200 Series Router.
- Cisco 7300 Series Router (with Network Processing Engine [NPE] processor).
- Cisco 7500 Series Router.

## FOR MORE INFORMATION

- For more information about Cisco Optimized Edge Routing, visit <a href="http://www.cisco.com/go/oer">http://www.cisco.com/go/oer</a> or contact your local account representative or <a href="mailto:cs-oer@cisco.com">cs-oer@cisco.com</a>.
- For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod\_end\_of\_life.html
- To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



**Corporate Headquarters** 

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com

Tel: 408 526-4000

800 553-NETS (6387) Fax: 408 526-4100 **European Headquarters** 

Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883 Asia Pacific Headquarters

Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777

Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <a href="https://www.cisco.com/go/offices">www.cisco.com/go/offices</a>.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, Pro-Connect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems. Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R)

205224.bo\_ETMG\_LF\_4.05

Printed in the USA