



The bridge to possible

Product End-of-Life Notice

Cisco public

# End-of-Sale and End-of-Life Announcement for the Cisco Lancope Legacy Appliances and Services

---

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	36
For more information	37

## Overview

### EOL12039 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Lancop Legacy Appliances and Services. The last day to order the affected product(s) is December 31, 2017. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

### End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Lancop Legacy Appliances and Services

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 1, 2017
<b>End-of-Sale Date: HW, App SW, License</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 31, 2017
<b>Last Ship Date: HW, App SW, License</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 31, 2018
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 31, 2018
<b>End of New Service Attachment Date: HW, App SW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 31, 2018
<b>End of Service Contract Renewal Date: App SW</b>	The last date to extend or renew a service contract for the product.	March 28, 2020
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	March 28, 2022
<b>Last Date of Support: HW, App SW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2022

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-FPS-1K-RED-M</b>	1 Month CONTRACT SUP FOR SW-1000FPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-100K-REDM</b>	1 Month CONTRACT SUP FOR SW-100KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-10K-RED-M</b>	1 Month CONTRACT SUP FOR SW-10KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-25K-RED-M</b>	1 Month CONTRACT SUP FOR SW-25KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-50K-RED-M</b>	1 Month CONTRACT SUP FOR SW-50KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-1K-RED</b>	1 Year CONTRACT SUP FOR SW-1000FPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-100K-RED</b>	1 Year CONTRACT SUP FOR SW-100KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-10K-RED</b>	1 Year CONTRACT SUP FOR SW-10KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-25K-RED</b>	1 Year CONTRACT SUP FOR SW-25KFPS-RED	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-50K-RED</b>	1 Year CONTRACT SUP FOR SW-50KFPS-RED	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-LC-UDP2K-F</b>	1 Year Maintenance for UD-20XX-F	There is currently no replacement product available for this product.	-	-
<b>CON-FC4K-NFU-VE</b>	1 Year Maintenance for FC2K-NF VE series upgrade	There is currently no replacement product available for this product.	-	-
<b>CON-FC4K-NFU2-VE</b>	1 Year Maintenance for FC4K-NF VE series upgrade	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP1K-C</b>	1 Year Maintenance for LC-UDP-K9, 1K C series	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP2K-C</b>	1 Year Maintenance for LC-UDP-K9, 2K C series	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP2K-C-U</b>	1 Year Maintenance for LC-UDP-K9, 2K C series Upgrades	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP2K-F-U</b>	1 Year Maintenance for UD-20XX-F upgrade	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP-VE</b>	1 Year Maintenance for UDP VE	There is currently no replacement product available for this product.	-	-
<b>CON-LC-STARTER</b>	1 Year maintenance for SMC VE Upgrade	There is currently no replacement product available for this product.	-	-
<b>CON-FC2K-U-VE</b>	1 Year maintenance for upgrading FC VE to FC2K VE	There is currently no replacement product available for this product.	-	-
<b>LC-SLIC-FC-1K</b>	1 Year maintenance on SLIC for FC 1K	See Product Migration Options section for details.	L-LC-TI-FC1K=	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>L-LC-SLIC-FC-1K-VE</b>	1 Year maintenance on SLIC for FC 1K VE	There is currently no replacement product available for this product.	-	-
<b>L-LC-SLIC-FC1K-VE=</b>	1 Year maintenance on SLIC for FC 1K VE	There is currently no replacement product available for this product.	-	-
<b>LC-SLIC-FC-2K</b>	1 Year maintenance on SLIC for FC 2K	See Product Migration Options section for details.	L-LC-TI-FC2K=	-
<b>L-LC-SLIC-FC-2K-VE</b>	1 Year maintenance on SLIC for FC 2K VE	There is currently no replacement product available for this product.	-	-
<b>LC-SLIC-FC-4K</b>	1 Year maintenance on SLIC for FC 4K	See Product Migration Options section for details.	L-LC-TI-FC4K=	-
<b>L-LC-SLIC-FC-4K-VE</b>	1 Year maintenance on SLIC for FC 4K VE	There is currently no replacement product available for this product.	-	-
<b>LC-SLIC-FC-5K</b>	1 Year maintenance on SLIC for FC 5K	There is currently no replacement product available for this product.	-	-
<b>L-LC-SLIC-FC-5K</b>	1 Year maintenance on SLIC for FC 5K VE	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-100K=</b>	1 Yr Renewal Support for L-LC-FPS-100K= from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-10K=</b>	1 Yr Renewal Support for L-LC-FPS-10K= from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-1K=</b>	1 Yr Renewal Support for L-LC-FPS-1K= from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-25K=</b>	1 Yr Renewal Support for L-LC-FPS-25K= from Lancope	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-FPS-50K=</b>	1 Yr Renewal Support for L-LC-FPS-50K= from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FSVE-VMW=</b>	1 Yr Renewal Support for L-LC-FSVE-VMW-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-SMC-VE=</b>	1 Yr Renewal Support for L-LC-SMC-VE-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FS2K-5C=</b>	1 Yr Renewal Support for LC-FS-2000-5C-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FS250-2C=</b>	1 Yr Renewal Support for LC-FS-250-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FS3K-2F=</b>	1 Yr Renewal Support for LC-FS-3000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FS4K-4F=</b>	1 Yr Renewal Support for LC-FS-4000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-SMC-2K=</b>	1 Yr Renewal Support for LC-SMC-2000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FC-NF-VE=</b>	1 Yr Renewal Support for L-LC-FC-NF-VE-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-SMC-1K=</b>	1 Yr Renewal Support for LC-SMC-1000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FC-NF-VE</b>	1 Yr Support for L-LC-FC-NF-VE-K9 from Lancope	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-FC2K-NF-VE</b>	1 Yr Support for L-LC-FC2K-NF-VE-K9 from Lancope		-	-
<b>CON-FC4K-NF-VE</b>	1 Yr Support for L-LC-FC4K-NF-VE-K9 from Lancope		-	-
<b>CON-FPS-100K</b>	1 Yr Support for L-LC-FPS-100K= from Lancope		-	-
<b>CON-FPS-10K</b>	1 Yr Support for L-LC-FPS-10K= from Lancope		-	-
<b>CON-FPS-1K</b>	1 Yr Support for L-LC-FPS-1K= from Lancope		-	-
<b>CON-FPS-25K</b>	1 Yr Support for L-LC-FPS-25K= from Lancope		-	-
<b>CON-FPS-50K</b>	1 Yr Support for L-LC-FPS-50K= from Lancope		-	-
<b>CON-FSVE-VMW</b>	1 Yr Support for L-LC-FSVE-VMW-K9 from Lancope		-	-
<b>CON-SMC-RED-VE</b>	1 Yr Support for L-LC-SMC-RED-VE-K9 from Lancope		-	-
<b>CON-SMC-VE</b>	1 Yr Support for L-LC-SMC-VE-K9 from Lancope		-	-
<b>CON-FS2K-5C</b>	1 Yr Support for LC-FS-2000-5C-K9 from Lancope		-	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-FS250-2C</b>	1 Yr Support for LC-FS-250-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FS3K-2F</b>	1 Yr Support for LC-FS-3000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-FS4K-4F</b>	1 Yr Support for LC-FS-4000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-SMC-1K</b>	1 Yr Support for LC-SMC-1000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>CON-SMC-2K</b>	1 Yr Support for LC-SMC-2000-K9 from Lancope	There is currently no replacement product available for this product.	-	-
<b>LC-FC-HDD-1.2TB</b>	1.2 TB 12G SAS 10K rpm SFF HDD	There is currently no replacement product available for this product.	-	-
<b>LC-FC-HDD-1.2TB=</b>	1.2 TB 12G SAS 10K rpm SFF HDD	There is currently no replacement product available for this product.	-	-
<b>LC-FC-PWR-AC-1200W</b>	1200W / 800W V2 AC Power Supply for 2U C-Series Servers	There is currently no replacement product available for this product.	-	-
<b>LC-FC-PWR-AC1200W</b>	1200W / 800W V2 AC Power Supply for 2U C-Series Servers	There is currently no replacement product available for this product.	-	-
<b>LC-FC-PWR-AC1200W=</b>	1200W / 800W V2 AC Power Supply for 2U C-Series Servers	There is currently no replacement product available for this product.	-	-
<b>LC-FC-MEM-1X162RU</b>	16GB DDR4-2133-MHz RDIMM/PC4-17000/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-PXY-100-M</b>	1MN CONTRACT FOR L-LC-PXY-100		-	-
<b>CON-PXY-100K-M</b>	1MN CONTRACT FOR L-LC-PXY-100K		-	-
<b>CON-PXY-10K-M</b>	1MN CONTRACT FOR L-LC-PXY-10K		-	-
<b>CON-PXY-1K-M</b>	1MN CONTRACT FOR L-LC-PXY-1K		-	-
<b>CON-PXY-25K-M</b>	1MN CONTRACT FOR L-LC-PXY-25K		-	-
<b>CON-PXY-50K-M</b>	1MN CONTRACT FOR L-LC-PXY-50K		-	-
<b>CON-FC5K-U-M</b>	1MN CONTRACT FOR SW-FC-5010-UPG		-	-
<b>CON-PXY-100</b>	1YR CONTRACT SUP FOR L-LC-PXY-100		-	-
<b>CON-PXY-100K</b>	1YR CONTRACT SUP FOR L-LC-PXY-100K		-	-
<b>CON-PXY-10K</b>	1YR CONTRACT SUP FOR L-LC-PXY-10K		-	-
<b>CON-PXY-1K</b>	1YR CONTRACT SUP FOR L-LC-PXY-1K		-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-PXY-25K</b>	1YR CONTRACT SUP FOR L-LC-PXY-25K	There is currently no replacement product available for this product.	-	-
<b>CON-PXY-50K</b>	1YR CONTRACT SUP FOR L-LC-PXY-50K	There is currently no replacement product available for this product.	-	-
<b>CON-SMC-2010-RED</b>	1YR CONTRACT SUP FOR SW-SMC-20XX-RED	There is currently no replacement product available for this product.	-	-
<b>LC-FC-HD300G</b>	300GB 6Gb SAS 10K RPM SFF HDD/hot plug/drive sled mounted	There is currently no replacement product available for this product.	-	-
<b>LC-FC-HD300G=</b>	300GB 6Gb SAS 10K RPM SFF HDD/hot plug/drive sled mounted	There is currently no replacement product available for this product.	-	-
<b>LC-FC-MEM-1X322RU</b>	32GB DDR4-2133-MHz RDIMM/PC4-17000/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
<b>L-LC-CHECK&amp;TUNE</b>	5 day fixed outcome service for Health Check and Tuning	There is currently no replacement product available for this product.	-	-
<b>L-LC-INTIAL</b>	5 day fixed outcome service for Initial Installation	There is currently no replacement product available for this product.	-	-
<b>LC-FC-PWR-AC-770W</b>	770W AC Hot-Plug Power Supply for 1U C-Series Rack Server	There is currently no replacement product available for this product.	-	-
<b>LC-FC-PWR-AC-770W=</b>	770W AC Hot-Plug Power Supply for 1U C-Series Rack Server	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC-BND-VE-K9</b>	Bundle FC for use with UA BND Bundles	See Product Migration Options section for details.	ST-FR-BUN	-
<b>L-LC-SMC-BND-VE-K9</b>	Bundle SMC for use with UA Bundles	See Product Migration Options section for details.	ST-FR-BUN	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FC-CPU-E52695D</b>	CPU 2.30 GHz E5-2695 v3/120W 14C/35MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
<b>LC-FC-CPU-E52680D</b>	CPU 2.50 GHz E5-2680 v3/120W 12C/30MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
<b>LC-12G-HDD-1.2TB=</b>	Cisco 1.2TB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 12G	There is currently no replacement product available for this product.	-	-
<b>LC-13G-HDD-1.2TB-</b>	Cisco 1.2TB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 13G	There is currently no replacement product available for this product.	-	-
<b>LC-13G-HDD-1.2TB=</b>	Cisco 1.2TB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FC-MRAID12G</b>	Cisco 12G SAS Modular Raid Controller	There is currently no replacement product available for this product.	-	-
<b>LC-FC-MRAID12G-2GB</b>	Cisco 12Gbps SAS 2GB FBWC Cache module (Raid 0/1/5/6)	There is currently no replacement product available for this product.	-	-
<b>LC-FC-MRAID12G-4GB</b>	Cisco 12Gbps SAS 4GB FBWC Cache module (Raid 0/1/5/6)	There is currently no replacement product available for this product.	-	-
<b>LC-13G-HDD-300GB-</b>	Cisco 300GB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 13G	There is currently no replacement product available for this product.	-	-
<b>LC-13G-HDD-300GB=</b>	Cisco 300GB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 13G	There is currently no replacement product available for this product.	-	-
<b>LC-12G-HDD-300GB=</b>	Cisco 300GB 15K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 12G	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-12G-HDD-600GB=</b>	Cisco 600GB 10K RPM SAS 6Gbps 2.5in Hot-plug Hard Drive, 12G	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-RED-S1</b>	Cisco Redundant Stealthwatch 1000 Collection License, 1-9	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-RED-S2</b>	Cisco Redundant Stealthwatch 1000 Collection License, 10-24	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-RED-S5</b>	Cisco Redundant Stealthwatch 1000 Collection License, 100+	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-RED-S3</b>	Cisco Redundant Stealthwatch 1000 Collection License, 25-49	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-RED-S4</b>	Cisco Redundant Stealthwatch 1000 Collection License, 50-99	There is currently no replacement product available for this product.	-	-
<b>LC-TOKEN-FC5020</b>	Cisco StealthWatch Activation Token	There is currently no replacement product available for this product.	-	-
<b>LC-RAILS=</b>	Cisco StealthWatch Sliding Rail Without Cable Management Arm	There is currently no replacement product available for this product.	-	-
<b>LC-FPS100-S1-LIC</b>	Cisco Stealthwatch 100 Collection License, 1-49	There is currently no replacement product available for this product.	-	-
<b>LC-FPS100-S3-LIC</b>	Cisco Stealthwatch 100 Collection License, 100-249	There is currently no replacement product available for this product.	-	-
<b>LC-FPS100-S4-LIC</b>	Cisco Stealthwatch 100 Collection License, 250-499	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FPS100-S2-LIC</b>	Cisco Stealthwatch 100 Collection License, 50-99	There is currently no replacement product available for this product.	-	-
<b>LC-FPS100-S5-LIC</b>	Cisco Stealthwatch 100 Collection License, 500+	There is currently no replacement product available for this product.	-	-
<b>LC-PXY100-S1-LIC</b>	Cisco Stealthwatch 100 ProxyWatch License, 1-9	There is currently no replacement product available for this product.	-	-
<b>LC-PXY100-S2-LIC</b>	Cisco Stealthwatch 100 ProxyWatch License, 10-99	There is currently no replacement product available for this product.	-	-
<b>LC-PXY100-S3-LIC</b>	Cisco Stealthwatch 100 ProxyWatch License, 100-249	There is currently no replacement product available for this product.	-	-
<b>LC-PXY100-S6-LIC</b>	Cisco Stealthwatch 100 ProxyWatch License, 1000+	There is currently no replacement product available for this product.	-	-
<b>LC-PXY100-S4-LIC</b>	Cisco Stealthwatch 100 ProxyWatch License, 250-499	There is currently no replacement product available for this product.	-	-
<b>LC-PXY100-S5-LIC</b>	Cisco Stealthwatch 100 ProxyWatch License, 500-999	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-S1-LIC</b>	Cisco Stealthwatch 1000 Collection License, 1-9	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-S2-LIC</b>	Cisco Stealthwatch 1000 Collection License, 10-24	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-S5-LIC</b>	Cisco Stealthwatch 1000 Collection License, 100+	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FPS1000-S3-LIC</b>	Cisco Stealthwatch 1000 Collection License, 25-49	There is currently no replacement product available for this product.	-	-
<b>LC-FPS1000-S4-LIC</b>	Cisco Stealthwatch 1000 Collection License, 50-99	There is currently no replacement product available for this product.	-	-
<b>LC-13-PWR-AC-750W-</b>	Cisco Stealthwatch 13G 750W AC Power Supply, Hot-plug	There is currently no replacement product available for this product.	-	-
<b>LC-13-PWR-AC-750W=</b>	Cisco Stealthwatch 13G 750W AC Power Supply, Hot-plug	There is currently no replacement product available for this product.	-	-
<b>LC-PWR-AC-1100W=</b>	Cisco Stealthwatch Dual 1100W AC Power Supply, Hot-plug, 12G	There is currently no replacement product available for this product.	-	-
<b>LC-PWR-AC-750W=</b>	Cisco Stealthwatch Dual 750W AC Power Supply, Hot-plug, 12G	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF1010-RMA</b>	Cisco Stealthwatch FC NF 1010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF2010-RMA</b>	Cisco Stealthwatch FC NF 2010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF4010-RMA</b>	Cisco Stealthwatch FC NF 4010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF5000-D-RMA</b>	Cisco Stealthwatch FC NF 5000 Diode Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF5000-E-RMA</b>	Cisco Stealthwatch FC NF 5000 Engine Install Base Migration	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FCNF5020-D-RMA</b>	Cisco Stealthwatch FC NF 5020 Diode Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF5020-E-RMA</b>	Cisco Stealthwatch FC NF 5020 Engine Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCSF1010-RMA</b>	Cisco Stealthwatch FC SF 1010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCSF2010-RMA</b>	Cisco Stealthwatch FC SF 2010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FCSF4010-RMA</b>	Cisco Stealthwatch FC SF 4010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FS1010-RMA</b>	Cisco Stealthwatch FS 1010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FS2010-C-RMA</b>	Cisco Stealthwatch FS 2010 Copper for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FS2010-F-RMA</b>	Cisco Stealthwatch FS 2010 Fiber for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FS3010-RMA</b>	Cisco Stealthwatch FS 3010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FS4010-RMA</b>	Cisco Stealthwatch FS 4010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-FC1K-LIC</b>	Cisco Stealthwatch Flow Collector 1K	There is currently no replacement product available for this product.	-	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FC2K-LIC</b>	Cisco Stealthwatch Flow Collector 2K	There is currently no replacement product available for this product.	-	-
<b>LC-FC4K-LIC</b>	Cisco Stealthwatch Flow Collector 4K	There is currently no replacement product available for this product.	-	-
<b>LC-FC5K-LIC</b>	Cisco Stealthwatch Flow Collector 5K	There is currently no replacement product available for this product.	-	-
<b>LC-FS1010</b>	Cisco Stealthwatch Flow Sensor 1010	There is currently no replacement product available for this product.	-	-
<b>LC-FS1K-LIC</b>	Cisco Stealthwatch Flow Sensor 1K	There is currently no replacement product available for this product.	-	-
<b>LC-FS2010-C</b>	Cisco Stealthwatch Flow Sensor 2010 Copper	There is currently no replacement product available for this product.	-	-
<b>LC-FS2010-F</b>	Cisco Stealthwatch Flow Sensor 2010 Fiber	There is currently no replacement product available for this product.	-	-
<b>LC-FS2K-LIC</b>	Cisco Stealthwatch Flow Sensor 2K	There is currently no replacement product available for this product.	-	-
<b>LC-FS3010</b>	Cisco Stealthwatch Flow Sensor 3010	There is currently no replacement product available for this product.	-	-
<b>LC-FS3K-LIC</b>	Cisco Stealthwatch Flow Sensor 3K	There is currently no replacement product available for this product.	-	-
<b>LC-FS4010</b>	Cisco Stealthwatch Flow Sensor 4010	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FS4K-LIC</b>	Cisco Stealthwatch Flow Sensor 4K	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF1010</b>	Cisco Stealthwatch FlowCollector for NetFlow 1010	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF2010</b>	Cisco Stealthwatch FlowCollector for NetFlow 2010	There is currently no replacement product available for this product.	-	-
<b>LC-FCNF4010</b>	Cisco Stealthwatch FlowCollector for NetFlow 4010	There is currently no replacement product available for this product.	-	-
<b>LC-FCSF1010</b>	Cisco Stealthwatch FlowCollector for sFlow 1010	There is currently no replacement product available for this product.	-	-
<b>LC-FCSF2010</b>	Cisco Stealthwatch FlowCollector for sFlow 2010	There is currently no replacement product available for this product.	-	-
<b>LC-FCSF4010</b>	Cisco Stealthwatch FlowCollector for sFlow 4010	There is currently no replacement product available for this product.	-	-
<b>LC-ID1100-RMA</b>	Cisco Stealthwatch Identity 1100 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-SMC1K-LIC</b>	Cisco Stealthwatch Management Console 1K	There is currently no replacement product available for this product.	-	-
<b>LC-SMC1010</b>	Cisco Stealthwatch Management Console 1K Appliance	There is currently no replacement product available for this product.	-	-
<b>LC-SMC2K-LIC</b>	Cisco Stealthwatch Management Console 2K	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-SMC2010</b>	Cisco Stealthwatch Management Console 2K Appliance	There is currently no replacement product available for this product.	-	-
<b>LC-SMC1010-RMA</b>	Cisco Stealthwatch SMC 1010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-SMC2010-RMA</b>	Cisco Stealthwatch SMC 2010 for Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>SF-LC-SW-K9</b>	Cisco Stealthwatch Software	There is currently no replacement product available for this product.	-	-
<b>LC-UD1010-RMA</b>	Cisco Stealthwatch UDP Director 1010 Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-UD2010-C-RMA</b>	Cisco Stealthwatch UDPD 2010 Copper Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-UD2010-F-RMA</b>	Cisco Stealthwatch UDPD 2010 Fiber Install Base Migration	There is currently no replacement product available for this product.	-	-
<b>LC-UD1010</b>	Cisco Stealthwatch UDPD Director 1010	There is currently no replacement product available for this product.	-	-
<b>LC-UD2010-C</b>	Cisco Stealthwatch UDPD Director 2010 Copper	There is currently no replacement product available for this product.	-	-
<b>LC-UD2010-F</b>	Cisco Stealthwatch UDPD Director 2010 Fiber	There is currently no replacement product available for this product.	-	-
<b>LC-FSVE-LIC</b>	Cisco Stealthwatch Virtual Edition Flow Sensor	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-UDVE-LIC</b>	Cisco Stealthwatch Virtual Edition UDP Director	There is currently no replacement product available for this product.	-	-
<b>LC-FC-N20-BBLKD</b>	Cisco UCS 2.5 inch HDD blanking panel	There is currently no replacement product available for this product.	-	-
<b>LC-FC-N20-BBLKD=</b>	Cisco UCS 2.5 inch HDD blanking panel	There is currently no replacement product available for this product.	-	-
<b>L-LC-SW-VE-CONV-K9</b>	Conversion from physical appliance to Virtual Edition	There is currently no replacement product available for this product.	-	-
<b>LC-FS-3010-U-K9</b>	Conversion to FlowSensor 3010-2F from FlowFlowSensor 20XX	There is currently no replacement product available for this product.	-	-
<b>LC-FS-4010-UPG-K9</b>	Conversion to FlowSensor 4010 from FlowSensor 30XX	There is currently no replacement product available for this product.	-	-
<b>LC-SMC-2010-U-K9</b>	Conversion to SMC 2K from SMC 1K	There is currently no replacement product available for this product.	-	-
<b>LC-SMC-2010-U1-K9</b>	Conversion to SMC 2K from SMC VE	There is currently no replacement product available for this product.	-	-
<b>LC-SMC-1010-CV-K9</b>	Conversion to Stealthwatch 1010 from SW VE	There is currently no replacement product available for this product.	-	-
<b>LC-FC-4010-U1-K9</b>	FC 1000 series upgrade to FC 4010	There is currently no replacement product available for this product.	-	-
<b>LC-FC-2010-U-K9</b>	FC 1010 upgrade to FC 2010	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FC-4010-U-K9</b>	FC 2000 series upgrade to FC 4010	There is currently no replacement product available for this product.	-	-
<b>CON-FC-4010-U</b>	FC 2K VE upgrade to FC 4010 appliance from FC 2010	There is currently no replacement product available for this product.	-	-
<b>LC-FC-1010-U-K9</b>	FC VE upgrade to FC 1010	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC2K-NFUVE-K9</b>	FC2K VE platform Upgrade from FCVE	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC4K-NFUVE-K9</b>	FC4K VE platform upgrade from FC VE	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC4KNFU2VE-K9</b>	FC4K VE platform upgrade from FC2K VE	There is currently no replacement product available for this product.	-	-
<b>LC-COLLECT-2000</b>	FlowCollector 2000; 2 TB storage; 60K fps; 1000 sources	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC4K-U2-VE-K9</b>	FlowCollector upgrade from FlowCollector VE to 4K VE	There is currently no replacement product available for this product.	-	-
<b>L-LC-COLLECT-VM</b>	FlowCollector virtual appl; 1 TB stor; 30K fps; 1K sources	There is currently no replacement product available for this product.	-	-
<b>LC-REP-2000-F</b>	FlowReplicator 2000; 2 FE/GE fiber; 20 KPPS in, 60 KPPS out	There is currently no replacement product available for this product.	-	-
<b>LC-SENS-2000-2F</b>	FlowSensor 2000 appliance; 3 FE/GE copper, 2 fiber, 2.5Gbps	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-SENS-2000</b>	FlowSensor 2000 appliance; 5 FE/GE copper, 2.5Gbps	There is currently no replacement product available for this product.	-	-
<b>LC-SENS-3000-F</b>	FlowSensor 3000 appliance; 1 10Gb fiber, 5Gbps	There is currently no replacement product available for this product.	-	-
<b>L-LC-SENS-VM</b>	FlowSensor virtual appl for VMware; monitors 1 ESXi/vSphere	There is currently no replacement product available for this product.	-	-
<b>CON-LC-GEN=</b>	General purpose renewal unit for legacy Stealthwatch	There is currently no replacement product available for this product.	-	-
<b>L-LC-INSTALL-FC5K</b>	Installation services recommended for purchase with the FC5K	There is currently no replacement product available for this product.	-	-
<b>L-LC-INSTALL-FC5K=</b>	Installation services recommended for purchase with the FC5K	There is currently no replacement product available for this product.	-	-
<b>LC-FC-N2XX-AIPCI01</b>	Intel X520 Dual Port 10Gb SFP+ Adapter	There is currently no replacement product available for this product.	-	-
<b>L-LC-100K-FPS</b>	Lancope Netflow collection license; 100K flows per sec	There is currently no replacement product available for this product.	-	-
<b>L-LC-10K-FPS</b>	Lancope Netflow collection license; 10K flows per sec	There is currently no replacement product available for this product.	-	-
<b>L-LC-1K-FPS</b>	Lancope Netflow collection license; 1K flows per sec	There is currently no replacement product available for this product.	-	-
<b>L-LC-25K-FPS</b>	Lancope Netflow collection license; 25K flows per sec	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>L-LC-50K-FPS</b>	Lancpe Netflow collection license; 50K flows per sec	There is currently no replacement product available for this product.	-	-
<b>LC-FS4K-UPG-K9</b>	Lancpe StealthWatch FlowSensor 4000 appliance Upgrade	There is currently no replacement product available for this product.	-	-
<b>LC-CONSOLE-1000</b>	Management Console 1000; 1 TB storage; monitors 5 Collectors	There is currently no replacement product available for this product.	-	-
<b>LC-CONSOLE-2000</b>	Management Console 2000; 2 TB storage; monitor 25 Collectors	There is currently no replacement product available for this product.	-	-
<b>LC-CONSOLE-500</b>	Management Console 500; 1 TB storage; monitors 1 Collector	There is currently no replacement product available for this product.	-	-
<b>L-LC-SMC1-VE-K9</b>	Management Console Virtual Edition for 1 Flow Collector	There is currently no replacement product available for this product.	-	-
<b>L-LC-CONSOLE-VM</b>	Management Console virtual appliance; 5 collectors; 1TB stor	There is currently no replacement product available for this product.	-	-
<b>CON-FC-SF-VE-M</b>	Option of 1 Month Maintenance for FC VE sFlow series	There is currently no replacement product available for this product.	-	-
<b>CON-FC1K-SF-M</b>	Option of 1 Month Maintenance for FC1K sFlow series	There is currently no replacement product available for this product.	-	-
<b>CON-FC2K-SF-M</b>	Option of 1 Month Maintenance for FC2K sFlow series	There is currently no replacement product available for this product.	-	-
<b>CON-FC4K-SF-M</b>	Option of 1 Month Maintenance for FC4K sFlow series	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-FPS-1K-M</b>	Option of 1 Month Maintenance for FPS 1K license	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-100K-M</b>	Option of 1 Month Maintenance for FPS-100K License	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-10K-M</b>	Option of 1 Month Maintenance for FPS-10K License	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-25K-M</b>	Option of 1 Month Maintenance for FPS-25K License	There is currently no replacement product available for this product.	-	-
<b>CON-FPS-50K-M</b>	Option of 1 Month Maintenance for FPS-50K License	There is currently no replacement product available for this product.	-	-
<b>CON-FS1K-M</b>	Option of 1 Month Maintenance for FS 1K series	There is currently no replacement product available for this product.	-	-
<b>CON-FS-VM-M-VE</b>	Option of 1 Month Maintenance for FS VE using VMWARE	There is currently no replacement product available for this product.	-	-
<b>CON-FS2K-3C2F-M</b>	Option of 1 Month Maintenance for FS2K 3C2F	There is currently no replacement product available for this product.	-	-
<b>CON-FS2K-5C-M</b>	Option of 1 Month Maintenance for FS2K 5C	There is currently no replacement product available for this product.	-	-
<b>CON-FS3K-2F-M</b>	Option of 1 Month Maintenance for FS3K 2F	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP1K-C-M</b>	Option of 1 Month Maintenance for LC-UDP-K9, 1K C series	There is currently no replacement product available for this product.	-	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-LC-UDP2K-C-M</b>	Option of 1 Month Maintenance for LC-UDP-K9, 2K C series	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP2K-F-M</b>	Option of 1 Month Maintenance for LC-UDP-K9, F series	There is currently no replacement product available for this product.	-	-
<b>CON-LC-UDP-M-VE</b>	Option of 1 Month Maintenance for LC-UDP-VE Series	There is currently no replacement product available for this product.	-	-
<b>CON-FC-NF-VE-M</b>	Option of 1 Month Maintenance for NF-FC VE series	There is currently no replacement product available for this product.	-	-
<b>CON-FC1K-NF-M</b>	Option of 1 Month Maintenance for NF-FC1K series	There is currently no replacement product available for this product.	-	-
<b>CON-FC2K-NF-VE-M</b>	Option of 1 Month Maintenance for NF-FC2K VE series	There is currently no replacement product available for this product.	-	-
<b>CON-FC2K-NF-M</b>	Option of 1 Month Maintenance for NF-FC2K series	There is currently no replacement product available for this product.	-	-
<b>CON-FC4K-NF-VE-M</b>	Option of 1 Month Maintenance for NF-FC4K VE series	There is currently no replacement product available for this product.	-	-
<b>CON-FC4K-NF-M</b>	Option of 1 Month Maintenance for NF-FC4K series	There is currently no replacement product available for this product.	-	-
<b>CON-FC5K-NF-M</b>	Option of 1 Month Maintenance for NF-FC5K series	There is currently no replacement product available for this product.	-	-
<b>CON-SMC1K-M</b>	Option of 1 Month Maintenance for SMC 1K	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CON-SMC-2K-M	Option of 1 Month Maintenance for SMC 2K	There is currently no replacement product available for this product.	-	-
CON-SMC-RED-M-VE	Option of 1 Month Maintenance for SMC redundant VE	There is currently no replacement product available for this product.	-	-
CON-LC-FC-OPT	Option of 1 Month for Coterming	There is currently no replacement product available for this product.	-	-
CON-LC-FPS-OPT	Option of 1 Month for Coterming	There is currently no replacement product available for this product.	-	-
CON-LC-FS-OPT	Option of 1 Month for Coterming	There is currently no replacement product available for this product.	-	-
CON-LC-PXY-OPT	Option of 1 Month for Coterming	There is currently no replacement product available for this product.	-	-
CON-LC-SMC-OPT	Option of 1 Month for Coterming	There is currently no replacement product available for this product.	-	-
CON-LC-UDP-OPT	Option of 1 Month for Coterming	There is currently no replacement product available for this product.	-	-
L-LC-PXY-100	ProxyWatch for up to 100 Users	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-PXY-1K	ProxyWatch for up to 1000 Users	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-PXY-10K	ProxyWatch for up to 10000 Users	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-PXY-100K	ProxyWatch for up to 100000 Users	See Product Migration Options section for details.	ST-FR-BUN	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>L-LC-PXY-25K</b>	ProxyWatch for up to 25000 Users	See Product Migration Options section for details.	ST-FR-BUN	-
<b>L-LC-PXY-50K</b>	ProxyWatch for up to 50000 Users	See Product Migration Options section for details.	ST-FR-BUN	-
<b>LC-SMC2K-RED-K9</b>	Redundant SMC-2000 appliance	There is currently no replacement product available for this product.	-	-
<b>L-LC-FPS-10K-RED</b>	Redundant StealthWatch Collection Lic, 10K flow per sec pack	There is currently no replacement product available for this product.	-	-
<b>L-LC-FPS-1K-RED</b>	Redundant StealthWatch Collection Lic, 1K flow per sec pack	There is currently no replacement product available for this product.	-	-
<b>L-LC-FPS-25K-RED</b>	Redundant StealthWatch Collection Lic, 25K flow per sec pack	There is currently no replacement product available for this product.	-	-
<b>L-LC-FPS-50K-RED</b>	Redundant StealthWatch Collection Lic, 50K flow per sec pack	There is currently no replacement product available for this product.	-	-
<b>L-LC-FPS-100K-RED</b>	Redundant StealthWatch Collection Lic, 100K flow per sec pack	There is currently no replacement product available for this product.	-	-
<b>LC-FPS-100K-RED</b>	Redundant StealthWatch Collection License, 100K	There is currently no replacement product available for this product.	-	-
<b>LC-FPS-10K-RED</b>	Redundant StealthWatch Collection License, 10K	There is currently no replacement product available for this product.	-	-
<b>LC-FPS-1K-RED</b>	Redundant StealthWatch Collection License, 1K	There is currently no replacement product available for this product.	-	-
<b>LC-FPS-25K-RED</b>	Redundant StealthWatch Collection License, 25K	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FPS-50K-RED</b>	Redundant StealthWatch Collection License, 50K	There is currently no replacement product available for this product.	-	-
<b>LC-FC-PCI-1B-240M4</b>	Right PCIe Riser Board (Riser 1) (3 x8) for 6 PCI slots	There is currently no replacement product available for this product.	-	-
<b>CON-SNT-LCFCNF59</b>	SNTC-8X5XNBD StealthWatch FlowCol	There is currently no replacement product available for this product.	-	-
<b>L-LC-SYSTINST</b>	SYSTEM INTEGRATION SVC For FlowCollector 5K	There is currently no replacement product available for this product.	-	-
<b>CON-LC-100-BND-VE</b>	StealthWatch 100 Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>CON-LC-1000-BND-VE</b>	StealthWatch 1000 Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-1000-BND-VEK9</b>	StealthWatch 1000FPS VE Appliance Bundle (UA BND)	See Product Migration Options section for details.	ST-FR-BUN	-
<b>L-LC-100-BND-VE-K9</b>	StealthWatch 100FPS VE Appliance Bundle (UA BND)	See Product Migration Options section for details.	ST-FR-BUN	-
<b>L-LC-100K-BND-VEK9</b>	StealthWatch 100K FPS VE Bundle	See Product Migration Options section for details.	ST-FR-BUN	-
<b>CON-LC-100K-BND-VE</b>	StealthWatch 100K Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-10K-BND-VE-K9</b>	StealthWatch 10K FPS VE Bundle	See Product Migration Options section for details.	ST-FR-BUN	-
<b>CON-LC-10K-BND-VE</b>	StealthWatch 10K Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-LC-200-BND-VE</b>	StealthWatch 200 Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-200-BND-VE-K9</b>	StealthWatch 200FPS VE Appliance Bundle (UA BND)	See Product Migration Options section for details.	ST-FR-BUN	-
<b>L-LC-25K-BND-VE-K9</b>	StealthWatch 25K FPS VE Bundle	See Product Migration Options section for details.	ST-FR-BUN	-
<b>CON-LC-25K-BND-VE</b>	StealthWatch 25K Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>CON-LC-300-BND-VE</b>	StealthWatch 300 Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-300-BND-VE-K9</b>	StealthWatch 300FPS VE Appliance Bundle (UA BND)	See Product Migration Options section for details.	ST-FR-BUN	-
<b>CON-LC-400-BND-VE</b>	StealthWatch 400 Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-400-BND-VE-K9</b>	StealthWatch 400FPS VE Appliance Bundle (UA BND)	See Product Migration Options section for details.	ST-FR-BUN	-
<b>CON-LC-500-BND-VE</b>	StealthWatch 500 Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-500-BND-VE-K9</b>	StealthWatch 500FPS VE Appliance Bundle (UA BND)	See Product Migration Options section for details.	ST-FR-BUN	-
<b>L-LC-50K-BND-VE-K9</b>	StealthWatch 50K FPS VE Bundle	See Product Migration Options section for details.	ST-FR-BUN	-
<b>CON-LC-50K-BND-VE</b>	StealthWatch 50K Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>L-LC-5K-BND-VE-K9</b>	StealthWatch 5K FPS VE Bundle	See Product Migration Options section for details.	ST-FR-BUN	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>CON-LC-5K-BND-VE</b>	StealthWatch 5K Maintenance incremental (UA BND)	There is currently no replacement product available for this product.	-	-
<b>LC-FC-1K-R-K9</b>	StealthWatch FlowCollector 10XX Hardware Refresh to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FC-2K-R-K9</b>	StealthWatch FlowCollector 20XX Hardware Refresh to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FC-4K-R-K9</b>	StealthWatch FlowCollector 40XX Hardware Refresh to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5020D-NF</b>	StealthWatch FlowCollector 5020 Dabase Node	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5020D-NF=</b>	StealthWatch FlowCollector 5020 Dabase for RMA Use Only	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5020E-NF</b>	StealthWatch FlowCollector 5020 Engine Node	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5020E-NF=</b>	StealthWatch FlowCollector 5020 Engine for RMA Use Only	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5000-NFU-K9</b>	StealthWatch FlowCollector Upgrade from 40XX to 5000	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5010-NFU-K9</b>	StealthWatch FlowCollector Upgrade from 40XX to 5010	There is currently no replacement product available for this product.	-	-
<b>LC-FC-2010-U1-K9</b>	StealthWatch FlowCollector Upgrade from VE to 2010	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FC-NF-5020-K9</b>	StealthWatch FlowCollector for 5020	There is currently no replacement product available for this product.	-	-
<b>LC-FC-1010-NF-K9</b>	StealthWatch FlowCollector for NetFlow 1010	See Product Migration Options section for details.	ST-FC4200-K9	-
<b>L-LC-FC1K-NF-VE-K9</b>	StealthWatch FlowCollector for NetFlow 1K Virtual Edition	There is currently no replacement product available for this product.	-	-
<b>LC-FC-2010-NF-K9</b>	StealthWatch FlowCollector for NetFlow 2010	See Product Migration Options section for details.	ST-FC4200-K9	-
<b>L-LC-FC2K-NF-VE</b>	StealthWatch FlowCollector for NetFlow 2K Virtual Edition	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC2K-NF-VE-K9</b>	StealthWatch FlowCollector for NetFlow 2K Virtual Edition	See Product Migration Options section for details.	L-ST-FC-VE-K9	-
<b>LC-FC-4010-NF-K9</b>	StealthWatch FlowCollector for NetFlow 4010	See Product Migration Options section for details.	ST-FC4200-K9	-
<b>L-LC-FC4K-NF-VE</b>	StealthWatch FlowCollector for NetFlow 4K Virtual Edition	There is currently no replacement product available for this product.	-	-
<b>L-LC-FC4K-NF-VE-K9</b>	StealthWatch FlowCollector for NetFlow 4K Virtual Edition	See Product Migration Options section for details.	L-ST-FC-VE-K9	-
<b>LC-FC-5010D-NFU-K9</b>	StealthWatch FlowCollector for NetFlow 5010 Appliance - DU	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5010E-NFU-K9</b>	StealthWatch FlowCollector for NetFlow 5010 Appliance - EU	There is currently no replacement product available for this product.	-	-
<b>LC-FC-5010-NF-K9</b>	StealthWatch FlowCollector for NetFlow 5010 Platform	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>L-LC-FC-NF-VE-K9</b>	StealthWatch FlowCollector for NetFlow Virtual Edition	See Product Migration Options section for details.	L-ST-FC-VE-K9	-
<b>L-LC-FC-SF-VE-K9</b>	StealthWatch FlowCollector for sFlow Virtual Edition	There is currently no replacement product available for this product.	-	-
<b>LC-UDP-1010-R-K9</b>	StealthWatch FlowReplicator 1K HW Refresh to UDP Dir. 1010	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-2010-R-K9</b>	StealthWatch FlowReplicator 20XX HW Refresh to UDP Dir. 2010	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-2010-FU1-K9</b>	StealthWatch FlowReplicator 20XX-F Hardware Refresh Program	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-2010-FU-K9</b>	StealthWatch FlowReplicator Dir Upg from 1010 to 2010 fiber	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-2010-C-U-K9</b>	StealthWatch FlowReplicator Dir Upg from 10XX to 2010 copper	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-1010-C-K9</b>	StealthWatch FlowReplicator Director 1010 Copper	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-2010-C-K9</b>	StealthWatch FlowReplicator Director 2010 Copper	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>LC-UDP-2010-F-K9</b>	StealthWatch FlowReplicator Director 2010 Fiber	See Product Migration Options section for details.	ST-UDP2200-K9	-
<b>L-LC-UDP-VE-K9</b>	StealthWatch FlowReplicator Director VE License	See Product Migration Options section for details.	L-ST-UDP-VE-K9	-
<b>L-LC-UDP-2010-VEK9</b>	StealthWatch FlowReplicator Director VE for 2010 License	There is currently no replacement product available for this product.	-	-
<b>LC-FS-1010-K9</b>	StealthWatch FlowSensor 1010	See Product Migration Options section for details.	ST-FS1200-K9	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-FS-1K-R-K9</b>	StealthWatch FlowSensor 10XX-F Hardware Refresh to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FS-2010-3C2F-K9</b>	StealthWatch FlowSensor 2010 3 Copper 2 Fiber	There is currently no replacement product available for this product.	-	-
<b>LC-FS-2010-5C-K9</b>	StealthWatch FlowSensor 2010 5 Copper	See Product Migration Options section for details.	ST-FS2200-K9	-
<b>LC-FS-2K-2R-K9</b>	StealthWatch FlowSensor 20XX-2F Hardware Refresh to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FS-2K-R-K9</b>	StealthWatch FlowSensor 20XX-F Hardware Refresh to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FS-3010-2F-K9</b>	StealthWatch FlowSensor 3010 2 Fiber 10G	See Product Migration Options section for details.	ST-FS3200-K9	-
<b>LC-FS-3K-R-K9</b>	StealthWatch FlowSensor 30XX Hardware Refresh Program to 13G	There is currently no replacement product available for this product.	-	-
<b>LC-FS-4010-4F-K9</b>	StealthWatch FlowSensor 4010 4 Fiber 10G	See Product Migration Options section for details.	ST-FS4200-K9	-
<b>LC-FS-4K-R-K9</b>	StealthWatch FlowSensor 40XX Hardware Refresh Program to 13G	There is currently no replacement product available for this product.	-	-
<b>L-LC-FSVE-VMW-K9</b>	StealthWatch FlowSensor virtual appliance for Vmware	See Product Migration Options section for details.	L-ST-FS-VE	-
<b>L-LC-SLIC-VE</b>	StealthWatch Labs Intelligence Center (SLIC) Feed for FC VE	There is currently no replacement product available for this product.	-	-
<b>L-LC-SLIC-VE=</b>	StealthWatch Labs Intelligence Center (SLIC) Feed for FC VE	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
L-LC-SLIC-FC2K	StealthWatch Labs Intelligence Center (SLIC) Feed for FC2KVE	There is currently no replacement product available for this product.	-	-
L-LC-SLIC-FC2K=	StealthWatch Labs Intelligence Center (SLIC) Feed for FC2KVE	There is currently no replacement product available for this product.	-	-
L-LC-SMC-VE-K9	StealthWatch Management Console Virtual Edition	See Product Migration Options section for details.	L-ST-SMC-VE-K9	-
L-LC-SMC-RED-VE-K9	StealthWatch Management Console Virtual Edition redundant pa	There is currently no replacement product available for this product.	-	-
LC-SMC-R-K9	StealthWatch Mgmt Console 10XX HW Refresh Program to 13G	There is currently no replacement product available for this product.	-	-
LC-SMC-2K-R-K9	StealthWatch Mgmt Console 20XX Hardware Refresh Program	There is currently no replacement product available for this product.	-	-
L-LC-SLIC-FC1K	StealthWatch SLIC Feed for FlowCollector 1K	There is currently no replacement product available for this product.	-	-
L-LC-SLIC-FC1K=	StealthWatch SLIC Feed for FlowCollector 1K	There is currently no replacement product available for this product.	-	-
L-LC-SLIC-FC4K	StealthWatch SLIC Feed for FlowCollector 4K	There is currently no replacement product available for this product.	-	-
L-LC-SLIC-FC4K=	StealthWatch SLIC Feed for FlowCollector 4K	See Product Migration Options section for details.	L-LC-TI-FC4K=	-
L-LC-SLIC-FC5K	StealthWatch SLIC Feed for FlowCollector 5K	There is currently no replacement product available for this product.	-	-
L-LC-SLIC-FC5K=	StealthWatch SLIC Feed for FlowCollector 5K	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
L-LC-BND1-VE-K9	StealthWatch Starter Bundle	There is currently no replacement product available for this product.	-	-
LC-TRAINING=	StealthWatch Training.	There is currently no replacement product available for this product.	-	-
L-LC-FPS-2K-VE	StealthWatch flow collection lic for 2K flows/sec Virtual	There is currently no replacement product available for this product.	-	-
L-LC-FPS-1K=	StealthWatch flow collection license for 1,000 flows/sec	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-FPS-10K=	StealthWatch flow collection license for 10,000 flows/sec	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-FPS-100K=	StealthWatch flow collection license for 100,000 flows/sec	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-FPS-25K=	StealthWatch flow collection license for 25,000 flows/sec	See Product Migration Options section for details.	ST-FR-BUN	-
L-LC-FPS-50K=	StealthWatch flow collection license for 50,000 flows/sec	See Product Migration Options section for details.	ST-FR-BUN	-
LC-FC-1010-SF-K9	StealthWatch sFlow Collector for 1010	There is currently no replacement product available for this product.	-	-
LC-FC-2010-SF-K9	StealthWatch sFlow Collector for 2010 Appliance Platform	There is currently no replacement product available for this product.	-	-
LC-FC-4010-SF-K9	StealthWatch sFlow Collector for 4010	There is currently no replacement product available for this product.	-	-
LC-FC-5020-NFU-K9	Stealthwatch FlowCollector Upgrade from 40XX to 5020	There is currently no replacement product available for this product.	-	-
LC-SMC-1010-K9	Stealthwatch Management Console 1010	See Product Migration Options section for details.	ST-SMC2200-K9	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>LC-SMC-1010-RED-K9</b>	Stealthwatch Management Console 1010 redundant	There is currently no replacement product available for this product.	-	-
<b>LC-SMC-2010-K9</b>	Stealthwatch Management Console 2010	See Product Migration Options section for details.	ST-SMC2200-K9	-
<b>LC-SMC-2010-RED-K9</b>	Stealthwatch Management Console Redundant SMC 2K	There is currently no replacement product available for this product.	-	-
<b>CON-LC-BND1-VE</b>	Support for L-LC-BND1-VE-K9	There is currently no replacement product available for this product.	-	-
<b>CON-LC-BND1-VE-K9</b>	Support for L-LC-BND1-VE-K9	There is currently no replacement product available for this product.	-	-
<b>L-LC-STARTER-VE</b>	UPG SMC FROM STARTER TO SMC-VE	There is currently no replacement product available for this product.	-	-

## Product migration options

Cisco Stealthwatch is migrating toward a subscription-based flow rate licensing model where services are included. In addition, the hardware appliances are transitioning toward a UCS-based appliance which will leverage Cisco's SMARTNET program for support. For more details on the Stealthwatch portfolio, please review the Stealthwatch Ordering Guide located:

<https://www.cisco.com/c/dam/en/us/products/collateral/security/stealthwatch/guide-c07-738299.pdf>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

[https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco Lancope Legacy Appliances and Services through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

---

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For more information

For more information about the Cisco End-of-Life Policy, go to:

[https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)