



End-of-Sale and End-of-Life Announcement for the Cisco Select Unified Computing Systems Accessories Spares

Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	17
For more information	17

Overview

EOL12712 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select Unified Computing Systems Accessories Spares. The last day to order the affected product(s) is February 14, 2020. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select Unified Computing Systems Accessories Spares

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 14, 2019
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 14, 2020
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 15, 2020
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	February 13, 2021
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 13, 2021
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	May 14, 2024
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 28, 2025

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-HD12G10K9=	1.2 TB 12G SAS 10K RPM SFF HDD (SED)	There is currently no replacement product available for this product.	-	-
HX-HD12TB10K12G=	1.2 TB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
HX-HD18TB10KS4K=	1.8 TB 12G SAS 10K RPM SFF HDD (4K)	There is currently no replacement product available for this product.	-	-
HX-SD38TBKS4-EV=	3.8TB 2.5 inch Enterprise Value 6G SATA SSD	There is currently no replacement product available for this product.	-	-
HX-SD38TBM1K9=	3.8TB Enterprise Value SSD (SATA) (1X FWPD, SED)	There is currently no replacement product available for this product.	-	-
HX-SD800GBEK9=	800GB Enterprise performance SAS SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
HX-SD960GBKS4-EV=	960GB 2.5 inch Enterprise Value 6G SATA SSD	There is currently no replacement product available for this product.	-	-
HX-SD960GBM1K9=	960GB Enterprise Value SSD (SATA) (1X FWPD, SED)	HX-SD960GBM2NK9=	960GB Enterprise value SATA SSD (1X, SED)	-
N20-BBLKD=	UCS 2.5 inch HDD blanking panel	There is currently no replacement product available for this product.	-	-
N2XX-AEPCI05=	Emulex LPe 12002, 8Gb dual port Fibre Channel HBA	There is currently no replacement product available for this product.	-	-
N2XX-AQPCI05=	Qlogic QLE2562 Dual Port 8Gb Fibre Channel HBA	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-220CBLPS8=	C220 M4 PCIe SSD cable (1) for 8 HDD backplane chassis	There is currently no replacement product available for this product.	-	-
UCS-220CBLSR4=	C220 M4 SATA/SW RAID cable (1) for 4 HDD backplane chassis	There is currently no replacement product available for this product.	-	-
UCS-220CBLSR8=	C220 M4 set of 2 SATA/SW RAID cables for 8HDD bckpln chassis	There is currently no replacement product available for this product.	-	-
UCS-300WK-240AMD=	300 Watt AMD Cable and Kit for UCS C240M4 Rack Server	There is currently no replacement product available for this product.	-	-
UCS-C3K-M4HBA=	Cisco UCS C3000 12G SAS HBA Controller for M4 Server Node	There is currently no replacement product available for this product.	-	-
UCS-C3K-M4RAID=	Cisco UCS C3000 RAID Controller M4 SrvNode w/4G RAID Cache	There is currently no replacement product available for this product.	-	-
UCS-CPU-CVR-EP-M4=	Unpopulated CPU sockets-dust cover for EP M4s	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4610E=	1.80 GHz E5-4610 v4/105W 10C/25MB Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4620E=	2.10 GHz E5-4620 v4/105W 10C/25MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4627E=	2.60 GHz E5-4627 v4/135W 10C/25MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4640E=	2.10 GHz E5-4640 v4/105W 12C/30MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-E5-4650E=	2.20 GHz E5-4650 v4/105W 14C/35MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4655E=	2.50 GHz E5-4655 v4/135W 8C/30MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4660E=	2.20 GHz E5-4660 v4/120W 16C/40MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4667E=	2.20 GHz E5-4667 v4/135W 18C/45MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E5-4669E=	2.20 GHz E5-4669 v4/135W 22C/55MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52609E=	1.70 GHz E5-2609 v4/85W 8C/20MB Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52620E=	2.10 GHz E5-2620 v4/85W 8C/20MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52623E=	2.60 GHz E5-2623 v4/85W 4C/10MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52630E=	2.20 GHz E5-2630 v4/85W 10C/25MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52630LE=	1.80 GHz E5-2630L v4/55W 8C/25MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52637E=	3.50 GHz E5-2637 v4/135W 4C/15MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-E52640E=	2.40 GHz E5-2640 v4/90W 10C/25MB Cache/DDR4 2133MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52643E=	3.40 GHz E5-2643 v4/135W 6C/20MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52650E=	2.20 GHz E5-2650 v4/105W 12C/30MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52650LE=	1.70 GHz E5-2650L v4/65W 14C/35MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52658E=	2.30 GHz E5-2658 v4/105W 14C/35MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52660E=	2.00 GHz E5-2660 v4/105W 14C/35MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52667E=	3.20 GHz E5-2667 v4/135W 8C/25MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52680E=	2.40 GHz E5-2680 v4/120W 14C/35MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52683E=	2.10 GHz E5-2683 v4/120W 16C/40MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52690E=	2.60 GHz E5-2690 v4/135W 14C/35MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52695E=	2.10 GHz E5-2695 v4/120W 18C/45MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-E52697AE=	2.60 GHz E5-2697A v4/145W 16C/40MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52697E=	2.30 GHz E5-2697 v4/145W 18C/45MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52698E=	2.20 GHz E5-2698 v4/135W 20C/50MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52699AE=	2.4 GHz E5-2699A v4/145W 22C/55MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E52699E=	2.20 GHz E5-2699 v4/145W 22C/55MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E74809E=	2.1 GHz E7-4809 v4/115W 8C/20M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E74820E=	2.0 GHz E7-4820 v4/115W 10C/25M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E74830E=	2.0 GHz E7-4830 v4/115W 14C/35M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E74850E=	2.1 GHz E7-4850 v4/115W 16C/40M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78860E=	2.2 GHz E7-8860 v4/140W 18C/45M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78867E=	2.4 GHz E7-8867 v4/165W 18C/45M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-E78870E=	2.1 GHz E7-8870 v4/140W 20C/50M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78880E=	2.2 GHz E7-8880 v4/150W 22C/55M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78890E=	2.2 GHz E7-8890 v4/165W 24C/60M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78891E=	2.8 GHz E7-8891 v4/165W 10C/60M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78893E=	3.2 GHz E7-8893 v4/140W 4C/60M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-CPU-E78894E=	2.4 GHz E7-8894 v4/165W 24C/60M Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	-	-
UCS-M4-V3-LBL=	Cisco M4 - v3 CPU asset tab ID label (Auto-Expand)	There is currently no replacement product available for this product.	-	-
UCS-M4-V4-LBL=	Cisco M4 - v4 CPU asset tab ID label (Auto-Expand)	There is currently no replacement product available for this product.	-	-
UCS-ML-1X644RU-G=	64 GB DDR4- 2133/2400-MHz LRDIMM/4R/x4/1.2v 1.2 4	There is currently no replacement product available for this product.	-	-
UCS-ML-1X644RV-A=	64GB DDR4-2400- MHz LRDIMM/PC4- 19200/quad rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X161RV-A=	16GB DDR4-2400- MHz RDIMM/PC4- 19200/single rank/x4/1.2v	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-MR-1X161RV-G=	16GB DDR4-2133MHz/2400-MHz RDIMM/single rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X161RVA++=	TAA compliant 16GB DDR4-2400-MHz RDIMM/PC4-19200/SR/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X161RVG++=	TAA compliant 16GB DDR4-2400-MHz RDIMM/PC4-19200/SR/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RU-G=	32 GB DDR4-2133/2400-MHz RDIMM/2R/x4/1.2v 1.2 2	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RUG++=	TAA compliant 32GB DDR4-2133-MHz RDIMM/PC4-17000/DR/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RUG-S=	32GB DDR4-2133-MHz RDIMM/PC4-17000/dual rank/x4/1.2v Samsung	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RV-A	32GB DDR4-2400-MHz RDIMM/PC4-19200/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RV-A=	32GB DDR4-2400-MHz RDIMM/PC4-19200/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RVA++=	TAA compliant 32GB DDR4-2400-MHz RDIMM/PC4-19200/DR/x4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-1X322RVA-S=	32GB DDR4-2400-MHz RDIMM/PC4-19200/dual rank/x4/1.2v Samsung	There is currently no replacement product available for this product.	-	-
UCS-MR-1X648RU-A=	64GB DDR4-2133-MHz TSV-RDIMM/PC4-17000/octal rank/x4/1.2v	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSB-BAFF-B200-M4=	Air Baffle Replacement Kit for B200 M4 Server.	There is currently no replacement product available for this product.	-	-
UCSB-EX-M4-2SC-2=	UCS Scalability Terminator for B260 M4 with v4 CPU	There is currently no replacement product available for this product.	-	-
UCSB-HS-EP-M4-F=	CPU Heat Sink for UCS B200 M4/B420 M4 (Front)	There is currently no replacement product available for this product.	-	-
UCSB-HS-EP-M4-R=	CPU Heat Sink for UCS B200 M4/B420 M4 (Rear)	There is currently no replacement product available for this product.	-	-
UCSB-HS-EX-L=	CPU Heatsink for UCS B260 M4 & B460 M4 Socket 1 (Left)	There is currently no replacement product available for this product.	-	-
UCSB-HS-EX-R=	CPU Heatsink for UCS B260 M4 & B460 M4 Socket 2 (Right)	There is currently no replacement product available for this product.	-	-
UCSC-300W-460AMD=	300 Watt AMD Cable for UCS C460M4 Rack Server	There is currently no replacement product available for this product.	-	-
UCSC-AUXCBL8-EX=	PCIe auxilliary power cable kit with adapter cable and 8-pin	There is currently no replacement product available for this product.	-	-
UCSC-BAFF-C460-M4=	Air Baffle for UCS C460 M4	There is currently no replacement product available for this product.	-	-
UCSC-BBLKD-L=	3.5-inch HDD Blanking Panel	There is currently no replacement product available for this product.	-	-
UCSC-BRCKT1-C420=	PCIe bracket for Cisco VIC 1225	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC-BRCKT1-C460=	Bracket and Supercap cable for C460 M4 and 12G RAID	There is currently no replacement product available for this product.	-	-
UCSC-BRCKT2-C420=	PCIe bracket for Cisco VIC (Kirkwood)	There is currently no replacement product available for this product.	-	-
UCSC-BRCKT2-C460=	Bracket and Supercap cable for C460 M4 and 12 drive RAID	There is currently no replacement product available for this product.	-	-
UCSC-BZL-C220M4=	C220 M4 Security Bezel	There is currently no replacement product available for this product.	-	-
UCSC-BZL-C240M4=	C240 M4 Security Bezel	There is currently no replacement product available for this product.	-	-
UCSC-BZL-EX=	Optional bezel for UCS C460 M4 rack server	There is currently no replacement product available for this product.	-	-
UCSC-CMA-4U=	Cable Management Arm for UCS C460 M4	There is currently no replacement product available for this product.	-	-
UCSC-HS-01-EX=	CPU Heat Sink for UCS C460 M4 Rack Server	There is currently no replacement product available for this product.	-	-
UCSC-HS-C220M4=	Heat sink for UCS C220 M4 rack servers	There is currently no replacement product available for this product.	-	-
UCSC-HS-C240M4=	Heat sink for UCS C240 M4 rack servers	There is currently no replacement product available for this product.	-	-
UCSC-IP-PCH-240M4=	Interposer board + cables for onboard PCH SATA 6G	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC-IP-SSD-240M4=	C240 M4 PCIE SSD Interposer bd + cable (8-16 drive config)	There is currently no replacement product available for this product.	-	-
UCSC-IPSSD-240M4B=	C240 M4 PCIE SSD Interposer bd + cable (24 drive config)	There is currently no replacement product available for this product.	-	-
UCSC-MLOM-BLK=	MLOM Blanking Panel	There is currently no replacement product available for this product.	-	-
UCSC-MLOM-C10T-02=	Cisco UCS VIC1227T VIC MLOM - Dual Port 10GBaseT	There is currently no replacement product available for this product.	-	-
UCSC-MLOM-CSC-02=	Cisco UCS VIC1227 VIC MLOM - Dual Port 10Gb SFP+	There is currently no replacement product available for this product.	-	-
UCSC-MRAID12G-1GB=	Cisco 12Gbps SAS 1GB FBWC Cache module (Raid 0/1/5/6)	There is currently no replacement product available for this product.	-	-
UCSC-MRAID12G-2GB=	Cisco 12Gbps SAS 2GB FBWC Cache module (Raid 0/1/5/6)	There is currently no replacement product available for this product.	-	-
UCSC-MRAID12G-4GB=	Cisco 12Gbps SAS 4GB FBWC Cache module (Raid 0/1/5/6)	There is currently no replacement product available for this product.	-	-
UCSC-MRAID12G-512=	Cisco 12Gbps SAS 512MB FBWC Cache module (Raid 0/1/5)	There is currently no replacement product available for this product.	-	-
UCSC-MRAID12G=	Cisco 12G SAS Modular Raid Controller	There is currently no replacement product available for this product.	-	-
UCSC-MRAIDC460=	Cisco 12G SAS Modular Raid Controller (12 port)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC-MRBD2-12=	UCS C460 M4 DDR4 Memory Riser with 12 DIMM slots	There is currently no replacement product available for this product.	-	-
UCSC-NVMEM4-H1600=	Cisco 2.5in U.2 1.6TB HGST SN200 NVMe. High Endurance SSD	There is currently no replacement product available for this product.	-	-
UCSC-NVMEM4-H800=	Cisco 2.5in U.2 800GB HGST SN200 NVMe. High Endurance SSD	There is currently no replacement product available for this product.	-	-
UCSC-PCI-1A-240M4=	Right PCIe Riser Board (Riser 1) (x8 + GPU) for C240 M4	There is currently no replacement product available for this product.	-	-
UCSC-PCI-1B-240M4=	Right PCIe Riser Board (Riser 1) (3 x8)	There is currently no replacement product available for this product.	-	-
UCSC-PCI-1C-240M4=	Right PCI Riser Bd (Riser 1) 2onbd SATA bootdrvs+ 2PCI slts	There is currently no replacement product available for this product.	-	-
UCSC-PCI-2-C240M4=	Left PCIe Riser Board (Riser 2) for C240 M4	There is currently no replacement product available for this product.	-	-
UCSC-PCI-2B-220M4=	C220 M4 PCIE SSD riser card kit and cables	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-C10T-02=	Cisco VIC 1225T Dual Port 10GBaseT Adapter	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-C40Q-02=	Cisco VIC 1285 Dual Port 40Gb QSFP Adapter	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-CSC-02=	Cisco VIC 1225 Dual Port 10Gb SFP+ CNA	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC-PCIE-E14102=	Emulex OCe14102-UX dual-port 10 GbE FCoE CNA	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-E14102B=	Emulex OCe14102B-UX dual-port 10G SFP+ with iSCSI, FCoE CNA	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-E16002=	Emulex LPe16002 Dual-Port 16Gb Fibre Channel HBA w/SR Optics	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-FLR-F=	Full Height PCIe slot filler for C Series	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-ITG=	Intel X540 Dual Port 10GBase-T Adapter	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-Q2672=	Qlogic QLE2672-CSC, 16Gb Fibre Channel HBA with SR Optics	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-QNICBT=	Qlogic QLE8442 dual-port 10GBase-T NIC	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-QNICSFP=	Qlogic QLE8442 dual-port 10G SFP+ NIC	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-RSR-05=	Riser card with 5 PCIe slots	There is currently no replacement product available for this product.	-	-
UCSC-PCIE-RSR-FLR=	PCIe Module Filler Panel for UCS C460 M4	There is currently no replacement product available for this product.	-	-
UCSC-PSAS12GHBA=	Cisco 12Gbps SAS Modular SAS HBA	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC-PSU2V2-1200W=	1200W / 800W V2 AC Power Supply for 2U C-Series Servers	There is currently no replacement product available for this product.	-	-
UCSC-PSU2V2-1400W=	1400W V2 AC Power Supply (200 - 240V) for 2U & 4U C Series	There is currently no replacement product available for this product.	-	-
UCSC-PSU2V2-650W=	650W V2 AC Power Supply for 2U C-Series Servers	There is currently no replacement product available for this product.	-	-
UCSC-PSU2V2-930DC=	930W V2 DC Power Supply for 2U C-Series Servers	There is currently no replacement product available for this product.	-	-
UCSC-PSUBLK-C460=	PSU Blanking Panel for C460 M4	There is currently no replacement product available for this product.	-	-
UCSC-RAIL-4U=	Rail Kit for UCS C460 M4	There is currently no replacement product available for this product.	-	-
UCSC-SAS12GHBA=	Cisco 12Gbps Modular SAS HBA	There is currently no replacement product available for this product.	-	-
UCSC-SAS9300-8E=	Cisco 12G SAS HBA with 8 external ports	There is currently no replacement product available for this product.	-	-
UCSC-SCCBL220=	Supercap cable 950mm	There is currently no replacement product available for this product.	-	-
UCSC-SCCBL240=	Supercap cable 250mm	There is currently no replacement product available for this product.	-	-
UCSC-SWRAID5=	Software Raid 5 upgrade key for embedded Raid	There is currently no replacement product available for this product.	-	-

Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Select Unified Computing Systems Accessories Spares through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to:

<https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to:

https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)