

End-of-Sale and End-of-Life Announcement for the Cisco 1 GHz Gainstar Amplifiers 55/70 and 65/86 Splits

EOL11562

Cisco announces the end-of-sale and end-of-life dates for the Cisco 1 GHz Gainstar Amplifiers 55/70 and 65/86 Splits. The last day to order the affected product(s) is August 22, 2017. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

Table 1. End-of-Life Milestones and Dates for the Cisco 1 GHz Gainstar Amplifiers 55/70 and 65/86 Splits

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 21, 2017
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 22, 2017
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 20, 2017
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	August 22, 2018
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 22, 2018
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	November 17, 2021
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	August 31, 2022

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4034474	GS Diplexer-65/87 (Pkg=10)	See the Product Migration Options section below for detailed information on replacing this product.	-	-
4040105	GS Diplexer-55/70 (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S512G53G01010000	GS Amp, 55/70-1G, Strand, Tilt/8dB, Rev/20, 60V	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S512G54201010000	GS AMP, 55/70-1G, S-H, FWD INJ, REV/23, 60V	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S512G60001010000	GS Amp, 65/87-1G, Strand, 60V, Fwd Only	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S512G60001020000	GS Amp, 65/87-1G, Ped, 60V, Fwd Only	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S512G63001010000	GS Amp, 65/87-1G, Strand, Rev/20, 60V	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S512G63001020000	GS Amp, 65/87-1G, Ped, Rev/20, 60V	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S711G60001010000	GS LE, 65/87-1G, Strand, 60V, Fwd Only	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S711G60001020000	GS LE, 65/87-1G, Ped, 60V, Fwd Only	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S711G63001010000	GS LE, 65/87-1G, Strand, Rev/20, 60V	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S711G63001020000	GS LE, 65/87-1G, Ped, Rev/20, 60V	See the Product Migration Options section below for detailed information on replacing this product.	-	-
S711G63002320000	GS LE, 65/87-1G, Ped, Rev/20, 220V, EU	See the Product Migration Options section below for detailed information on replacing this product.	-	-

Product Migration Options

The 55/70 and 65/86 MHz Split options for Gainstar 1 GHz amplifiers are being discontinued but we will continue to carry the other split options for the 1 GHz Gainstar products. We also offer GainMaker products as an alternative for Gainstar products.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco 1 GHz Gainstar Amplifiers 55/70 and 65/86 Splits through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod warranties listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Gisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-738613-00 02/17